

# Report of Survey for Repairs, &c., of Engines & Boilers.

49174

(Received at London Office.)

No. \_\_\_\_\_ Date of Writing Report Feb 4<sup>th</sup> 1889 Port of London MON 11 FEB 1889  
 No. in Reg. Book. 352 Survey held at London Date, first Survey Jan 30 Last Survey Jan 31<sup>st</sup> 1889  
 on the Machinery of the S.S. Pickwick Master \_\_\_\_\_ No. of Visits 2  
 Tonnage { Gross 1141 Vessel built at Sunderland By whom W. Pile & Co When 1871 Jan 8  
 Net 731 Engines made at M. E. Williams & Co When 1871 Boilers, when made (Main) 1880 (Donkey) 1880  
 Registered Horse Power 110 Owners C. C. Barton Port St. Shields Voyage \_\_\_\_\_  
 No. of Main Boilers 2 If Surveyed Afloat or in Dry Dock Centers Dry Dock Class of Vessel & Machinery GOA. 1288  
 Steam Pressure in Main Boilers 70 (State name of Dock.) Millwall Dock (as in Register Book.) L.M.C. 2.88.  
 in Donkey Boiler 44

Last Survey No. \_\_\_\_\_ Port \_\_\_\_\_

Particulars of Examination and Repairs (if any) Annual Boiler Survey  
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case

Did the Surveyor personally go inside each Boiler separately (including the Donkey Boiler, if any), and make a thorough examination at this time? Yes

If this was not done, state for what reasons? \_\_\_\_\_

And what parts of the Boilers could not be thus thoroughly examined? \_\_\_\_\_

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each boiler? \_\_\_\_\_

Examined all sea cocks and connections, propellers and ~~interior of~~ propeller-shaft and stern bush - all in good working order - stern bush relined with lignum-vitae.

Examined both main boilers internally and externally - both in sound condition - Examined steam chests main & Turkey safety valves and all check valves - all in good order -

Examined Turkey boiler internally and externally - blisters in funnel plate - Plate drilled and found sufficiently thick -

Feb. 8<sup>th</sup> Millwall Dock Adjusted the main safety valves to 70 lbs under steam The donkey boiler has been repaired by fitting a new flange at the connection between the furnace crown & the uptake, & a new doubling ring round the man hole.

" 11 Adjusted <sup>boiler</sup> winch valve to 44 lbs under steam

General Observations, Opinion, and Recommendation:— The machinery being now as seen in a sound & efficient condition renders the vessel eligible in my opinion to remain as classed & to have B.S.-1,89 now amended

Office or Registration Fee (per Sec. 27).....	£ : :	} Fees applied for <u>14 2 0</u> 1889
Survey Fee (per Section 25) .....	£ 2 : 2 : 0	
Special Damage, Fee (per Section 28) .....	£ : :	
Certificate (if required) as per margin .....	£ : :	
Travelling Expenses (if chargeable) .....	£ : :	} Received by me, <u>2/12</u> 1889

Herbert H. Gray  
Herbert H. Rogers  
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute FEBRUARY 15 FEB 1889  
 Assigned B S 1/89



State of a Report is also sent on the...

Insert Character of Ship and Machinery precisely as in the Register Book.

It is submitted that this vessel is eligible to have B.S. 1-89 recorded.

MA  
14.2.89

*[Faint, mostly illegible handwritten text, likely bleed-through from the reverse side of the page.]*

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2021

Lloyd's Register Foundation

STATIONER & PRINTER TO HIS MAJESTY THE KING