

Report of Survey for Repairs, &c., of Engines & Boilers.

No. *311* Date of Writing Report *October 28th 1889* Port of *London* (Received at London Office, *TUES 29 OCT 1889*)
 No. in Reg. Book. *311* Survey held at *London* Date, first Survey *Sept 11th* Last Survey *Oct 26th 1889*
 on the Machinery of the *S. S. Petrel* Master *Randall* No. of Visits *6*
 Tonnage Gross *841* Net *540* Vessel built at *London* By whom *Hall Russell* When *1876* Boilers, when made (Main) *1889* (Donkey) *1876*
 Registered Horse Power *99* Engines made at *"* When *1876* Boilers, when made (Main) *1889* (Donkey) *1876*
 No. of Main Boilers *1* Owners *General Steam Navigation Co* Port *London* Voyage *"*
 Steam Pressure in Main Boilers *65* If Surveyed Afloat or in Dry Dock *Septford* (State name of Dock.)
 in Donkey Boiler *50* Class of Vessel & Machinery (As in Register Book, including date of last Boiler Survey.) *100 A. 1. 6. 85*
L M C. 6. 85

Last Survey No. *"* Particulars of Examination and Repairs (if any) *Special*

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case

Did the Surveyor personally go inside each Boiler separately (including the Donkey Boiler, if any), and make a thorough examination at this time? *Yes*

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each boiler? *Boiler docked & sea connections & sea cocks all examined, new tail end shaft placed in position, propeller examined & found satisfactory*

Cylinders pistons, slide valves, cylinder faces, all pumps condenser crankshaft & all working parts of engines examined & found satisfactory

High pressure cylinder bored out & new piston ring fitted glands rebushed & piston & pump rods truck up minor repairs done to engines

Main & Donkey boiler & safety valves examined & found in order

Main safety valves tested to 65 lbs, Donkey boiler safety valves blew at 50 lbs

General Observations, Opinion, and Recommendation:— *The machinery of this vessel being now in an efficient state, she is eligible in my opinion to be classed L M C. 10. 89 in the Register Book*

Office or Registration Fee (per Sec. 27) £ : : Fees applied for
 Survey Fee (per Section 28) £ *4* : *10* : *2/10 1889*
 Special Damage Fee (per Section 28) £ : :
 *Certificate (if required) as per margin £ : : received by me, *19/11 1889*
 Travelling Expenses (if chargeable) £ : :
Maurice Wilson
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute *FRIDAY 1 NOV 1889*
 Assigned *L M C. 10. 89*
 © 2021 Lloyd's Register Foundation
 LON 087-0302

State if a Report is also now sent on the Ship or if not whether, and when, one will be sent.

T. & S. Form No. 2—Transfer Ink—6000, 28/1/89. * Certificate to be sent to (The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character of Ship and Machinery precisely as in the Register Book.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that this vessel is
eligible to have L.N.C. 10.89 and

~~N.B.~~ recorded.

N.A.
20-11-89

N.A.
31-10-89

