

Report of Survey for Repairs, &c., of Engines & Boilers.

50614
TUES 13 MAY 1890

No. _____ Date of Writing Report *May 12th 1890* Port of *London*
 No. in Reg. Book. Survey held at *London* Date, first Survey *April 30th* Last Survey *May 10th 1890*
 580 on the Machinery of the *A.D. Erasmus Wilson* Master *Bond* No. of Visits *4*
 Tonnage Gross *805* Net *494* Vessel built at *W. Hartlepool* By whom *E. Withy & Co* When *1876* YEAR. MONTH. *3*
 Registered Horse Power *99* Engines made at *Stockton* When *1876* Boilers, when made (Main) *1876* (Donkey)
 No. of Main Boilers *one* Owners *A. Clarke & Co* Port *London* Voyage *Coast*
 Steam Pressure in Main Boilers *70 lbs* If Surveyed *Afloat* or in Dry Dock *Regents* Class of Vessel & Machinery
 in Donkey Boiler *40 "* (State name of Dock.) (As in Register Book, including dates of Special Surveys of Ship and of last Boiler Survey.)

Last Survey No. _____ Port *A.D. Lon No 3 - 9.88* 90 A1.10.89
 Particulars of Examination and Repairs (if any) *Annual B.S. (Anticipated)* L.M.C. 9.88
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from

Repairs due to other causes. State also the dates and initials of any letters respecting this case _____

Did the Surveyor personally go inside each Boiler separately (including the Donkey Boiler, if any), and make a thorough examination at this time? *Yes*

If this was not done, state for what reasons? _____

And what parts of the Boilers could not be thus thoroughly examined? _____

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each boiler? _____

Sea connections & propeller fastenings examined & found in good condition

Examined main & donkey boilers & their respective safety-valves, new seats fitted to main safety-valves Patches put in centre combustion chamber, one on the back & the other on the starboard side, new screwed stays with nuts fitted through these patches

*Donkey safety-valves dead weighted & calculated to blow at 40 lbs per sq inch
 Main safety-valves set to the working pressure of 70 lbs*

General Observations, Opinion, and Recommendation:— *As far as seen this vessels machinery is in good condition & eligible in my opinion to remain as classed & to have B.S. 5.90 recorded in the Reg. Book*


Office or Registration Fee (per Sec. 27).....	£ : :	Fees applied for
Survey Fee (per Section 28).....	£ 1 10	13/5 1890
Special Damage Fee (per Section 28).....	£ : :	} <i>all</i>
*Certificate (if required) as per margin.....	£ : 2 : 6	
Travelling Expenses (if chargeable).....	£ : :	Received by me, <i>16/5 1890</i>

Maurice Wilson
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute *FRI 16 MAY 1890*
 Assigned *RS 5/90*

T. & S. Form No. 9 - Transfer Ink - 6006, 9 12 89
 *Certificate to be sent to
 The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character of Ship and Machinery precisely as in the Register Book.



It is submitted that this vessel is eligible to have B.S. 5. 90 recorded

M.L.
13. 5. 90

[Faint, illegible handwritten text, likely bleed-through from the reverse side of the page.]

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019
Lloyd's Register
Foundation