

50931

FRI 25 JULY 1890

Last Survey No. 9 Port Quincy
 Particulars of Examination and Repairs (if any) _____
 Special Surveys of Ship and of last Boiler Survey. + A. 1. 8. 89
S. S. No 3-1. 89 MS. 2. 88
DS. 7. 89

Did the Surveyor personally go inside each Boiler separately (including the Donkey Boiler, if any), and make a thorough examination at this time?

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each boiler?

Tail shaft examined, found to be much corroded & was condemned.

A new shaft - fitted, this was inspected during construction & stamped

It is submitted that this
Parcel is shght to
Remain as classed
I. J. M
28/7/90

(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey : thus, for example, B.S. 1/89, B. & M.S. 1/89, or ∇ L.M.C. 1/89, as the case may be.)

As far as seen in good condition, & eligible in my opinion
to remain as cleared

Graunce Pitson
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute

TUES 29 JULY 1890

Assigned

Remain no classes

LR

Lloyd's Register
Foundation

LON690 - 0219