

Report of Survey for Repairs, &c., of Engines & Boilers.

No. 420 Date of Writing Report 18 Port of London
 No. in Reg. Book 420 Survey held at London Date, first Survey Oct-30th Last Survey Nov 26th 1890
 on the Machinery of the S.S. "Grapple" Master Harriet No. of Visits 6
 Tonnage Gross 868 Net 498 Vessel built at Swanland By whom J. Laming When 1880 1
 Registered Horse Power 100 Engines made at Newcastle Boilers, when made (Main) 1880 (Donkey) 1880
 No. of Main Boilers One Owners M. T. & Panama Tel Co Ltd Port London Voyage
 Steam Pressure in Main Boilers 70 If Surveyed Afloat or in Dry Dock Turner's Dry Dock
 in Donkey Boiler 59 (State name of Dock.) Class of Vessel & Machinery
 (As in Register Book, including dates of Special Surveys of Ship and of last Boiler Survey.) +100 A. 5. 88
L.M.C. 6. 88

Last Survey No. 2 Port London 1888

Particulars of Examination and Repairs (if any) Annual Boiler survey & general repairs

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case

Did the Surveyor personally go inside each Boiler separately (including the Donkey Boiler, if any), and make a thorough examination at this time? Yes

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each boiler?

Main & donkey boilers & their respective safety valves examined
two or three new rivets put in comb chamber heads

Main safety valves blow at 70 lbs per sq inch
Donkey " " Calculated to " " 59 " " " " " dead wt^d
also lower wt^d

All pumps overhauled, buckets & valves tried up & new glands
& neck bushes fitted, tail shaft drawn & examined &
stem bush lined up, thrust shaft tried up in the locker
& thrust collars rubbed. General overhaul of engines
Examined crank shaft, a longitudinal flaw found in forward crank
pin, this flaw it is stated has not extended for two years, the depth at
the worst part is about an 1/4 inch, altogether this flaw is inconsiderable.

General Observations, Opinion, and Recommendation:-- as far as seen this vessel's

(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 1/89, B. & M.S. 1/89, or L.M.C. 1/89, as the case may be.)

machinery is in good condition, & she is eligible in my
opinion to remain as classed, & to have BS. 11. 90
recorded in the Regt book

Office or Registration Fee (per Sec. 27).....	£ : :	Fees applied for
Survey Fee (per Section 28)	£ 1 : 10:	25/11/1890
Special Damage Fee (per Section 28)	£ : :	
*Certificate (if required) as per margin	£ : 2 : 6	received by me,
Travelling Expenses (if chargeable).....	£ : :	10/12 1890

Harriet Wilson M.P. (London)
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute

Assigned

28 NOV 1890

13 8 11/90



© 2019

Lloyd's Register Foundation

LN691-0261

State of a ... is also now sent on the Ship ...

T. & S. Form No. 2—Transfer Ink—5500, 5/12/88. ...

Insert Character of Ship and Machinery precisely as in the Register Book

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that this
vessel is eligible to
have B.S. 11-90
recorded

M.A.
27-11-90



© 2019

Lloyd's Register
Foundation