

Report of Survey for Repairs, &c., of Engines & Boilers.

51461

(Received at London Office,

WED 14 JAN 1891)

No. *82* Date of Writing Report *13th Jan 1891* Port of *London*
 No. in Reg. Book *82* Survey held at *London* Date, first Survey *17th Dec^r* Last Survey *8th Jan 1891*
 on the Machinery of the *"Paradox"* Master *Cook* No. of Visits *9*
 Tonnage { Gross *603* Net *381* Vessel built at *London* By whom *Hillwall & Co. Dock* When *1883* YEAR. MONTH. *9*
 Registered Horse Power *98* Engines made at *New Castle* When *1877* Boilers, when made (Main) *1885* (Donkey) *1885*
 No. of Main Boilers *1* Owners *W. France & Co* Port *London* Voyage *✓*
 Steam Pressure in Main Boilers *45* If Surveyed Afloat or in Dry Dock *Ordn^y Dry dock* Class of Vessel & Machinery *+100 AI. 8,89*
 in Donkey Boiler *✓* (As in Register Book, including dates of Special Surveys of Ship and of last Boiler Survey.) *+NB 1.55 LMC 8.89*

Last Survey No. *51979* Port *S.S. Lou. N^o 3 8-89 Lon*

Particulars of Examination and Repairs (if any)

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case

Did the Surveyor personally go inside each Boiler separately (including the Donkey Boiler, if any), and make a thorough examination at this time?

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each boiler?

Examined propeller found good
" Tail end shaft found it much Corroded at for² end
of cone - also brass liner slack
Shaft put in lathe & turned up (to fit propeller further on
shaft-) which showed up a defective part - recommended
new end - which was done at the Thames Iron Works &
machined at Stewart's & brass liner fitted - satisfactory.
Shaft fitted in propeller before being shipped - satisfactory.
Examined sea connections & their fastenings - all good.
" Propeller & its fastening when fitted on board all
good.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 1/89, B. & M.S. 1/89, or L.M.C. 1/89, as the case may be.)

As far as seen the machinery
of this vessel is in good work² order and in my opinion eligible
to remain as classed

	£	:	:	Fees applied for
Office or Registration Fee (per Sec. 27)				18
Survey Fee (per Section 28)				
Special Damage Fee (per Section 28)				
*Certificate (if required) as per margin				Received by me,
Travelling Expenses (if chargeable)				

Robt. Balfour
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute *FRI 15 JAN 91*

Assigned *as now*



© 2019

Lloyd's Register Foundation

LON691-0437

State if a Report is also now sent in the Ship or if not whether, and when, one will be sent.

*Certificate to be sent to

T. & S. Form No. 9 - Transfer Book - 8000, 2/10/90

Insert Character of Ship and Machinery precisely as in the Register Book.

It is submitted that this vessel is eligible to remain as classed.

W.A.
15-1-91

[Faint, illegible handwritten notes and bleed-through from the reverse side of the page.]

