

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office) MON. 27 APR 1891

No. 51798 Date of Writing Report 24th April 1891 Port of London
 No. in Reg. Book. 40 Survey held at Millwall Date, first Survey April 7th Last Survey April 18th 1891
 on the Machinery of the s/s. "Fanny" Master R. Brown No. of Visits 4
 Gross Tonnage 208 Vessel built at Glasgow By whom A. J. Inglis When 1878 3
 Net Tonnage 192 Engines made at do: When 1878 Boilers, when made (Main) 1878 (Donkey) 1878
 Registered Horse Power 50 Owners J. Burnett & Sons Port London Voyage
 No. of Main Boilers one If Surveyed ~~At~~ in Dry Dock Regent Class of Vessel & Machinery +100A.1.2-91
 Steam Pressure in Main Boilers 70 lb. (State name of Dock.) (As in Register Book, including dates of Special Surveys of Ship and of last Boiler Survey.) B.S. 2-91
 in Donkey Boiler 50 lb. Last Survey No. 51759 Port Ldn. S.S. Ldn No 3-1-90 S.S. No 3-1-90 June 1-90

Particulars of Examination and Repairs (if any)

(State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

Sea-cock fastenings in good condition.

The combustion chamber ribs, having become thin round about the stays, have now been cut out, for a distance of about 18 inches and new plate has been riveted on satisfactorily - The boiler has also been re-tubed.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 1, 89, B.&M.S. 1, 89, or L.M.C. 1, 89, as the case may be.)

of this vessel is in good condition & reliable in my opinion to remain as classed in the register book.

Office or Registration Fee (per Sec. 27)	£	:	:	Fees applied for
Survey Fee (per Section 28)	£	:	:	18
Special Damage Fee (per Section 28)	£	:	:	Received by me,
Travelling Expenses (if chargeable)	£	:	:	18

*State if Certificate is Required

Committee's Minute

Assigned

FRI 1 MAY 1891
TUES 28 APR 1891

as now

H. P. Cornish
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register
 Foundation

State if a Report is also now sent on the Ship, or if not whether, and when one will be sent.

*Certificate to be sent to Committee's Minute.

15-L.R.F.H.-Form No. 9-Transfer Ink-1,000, 23-2-91.

Insert Character of Ship and Machinery precisely as in the Register Book.

It is submitted that this
vessel is eligible to remain
as classed

W. 4. 91
C. J. S.

