

Report of Survey for Repairs, &c., of Engines and Boilers.

No. *136* Date of Writing Report *July 1891* Port of *London*
 No. in Reg. Book. *136* Survey held at *London* Date, first Survey *July 1891* Last Survey *July 1891*
 on the Machinery of the *S.S. "Hawthorne"* Master *J. Fenwick & Sons* No. of Visits *4*
 Tonnage { Gross *437* Net *451* Vessel built at *Newcastle* By whom *J. Fenwick & Sons* When *1861*
 { Engines made at *"* When *1861* Boilers, when made (Main) *1873* (Donkey) *"*
 { Horse Power *95* Owners *J. Fenwick & Sons* Port *London* Voyage *"*
 No. of Main Boilers *2* If Surveyed Afloat or in Dry Dock *Afloat*
 Steam Pressure in Main Boilers *65* (State name of Dock.)
 in Donkey Boiler *"* Class of Vessel & Machinery
 Last Survey No. *136* Port *London* (As in Register Book, including dates of Special Surveys of Ship and of last Boiler Survey.) *A 1.1.91*

Particulars of Examination and Repairs (if any) *Damage & P.O. No. 1 P.O. Lon No 3 5-88 B.S. 6-90*

(State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? *Yes*

Do.	"	Donkey	"	"	"
-----	---	--------	---	---	---

If this was not done, state for what reasons?

and what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each boiler ?

Did the Surveyor examine the Safety Valves of the Main Boiler? *yes*

What pressure were they afterwards adjusted under steam? *Four weighed & cal - to show at 63 lbs*

Did the Surveyor examine the Safety Valves of Donkey Boiler?

what pressure were they afterwards adjusted?

Whirlt on a voyage from Shuldo to London on June 30th 1891 broke
tail shaft + stern tube.

A new Tail shaft & stern tube have been fitted

Examined cylinders, pistons, slide valves, shafting, & pump
leak-cocks. 3rd pump fitted with new valves & seats.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey, thus, for example, B.S. 189, E.&M.S. 189, or ~~X~~L.M.C. 189, as the case may be.)

thus, for example, B.S. 1,89, F.&M.S. 1,89, or ~~X~~L.M.C. 1,89, as the case may be.)
~~as far as~~ This vessel's machinery is now in good condition
 & she is eligible in our opinion to have Brms. 79 recorded
 in the Reg^d Book

Office or Registration Fee (per Sec. 27).....	£ 3 10 0	Fees applied for	22/7/91
Survey Fee (per Section 28).....	£ 2 4 4	Received by me,	23/7/91 (amended)
Special Damage Fee (per Section 28).....	£ 4 4 4		
Travelling Expenses (if chargeable).....	£ :		

Maurice Wilson & P. Cornish
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping

* State if Certificate is required.

Committee's Minute FEB 24 1962

Assigned BAMS 114

Len 693 - 02

It is submitted that this
vessel is eligible to
have B.M.S. 7-91
recorded.

W.A.

23-7-91



© 2019

Lloyd's Register
Foundation