

52383

# Report of Survey for Repairs, &c., of Engines and Boilers.

WED. 14 OCT 1891

(Received at London Office.....)

No. \_\_\_\_\_ Date of Writing Report October 1891 Port of LONDON

No. in Reg. Book. 73 Survey held at LONDON Date, first Survey Sept 21<sup>st</sup> Last Survey Sept 21<sup>st</sup> 1891  
 on the Machinery of the efs. "Danfield" Master G. Wright No. of Visits 1

Tonnage { Gross 734 Vessel built at Newcastle By whom Palmer B<sup>ts</sup> When 1864 12  
 Net 441 Engines <sup>made</sup> at do. When 1877 Boilers, when made (Main) 1877 (Donkey) -

Registered Horse Power 90 Owners Dunwick & Son Port LONDON Voyage \_\_\_\_\_

No. of Main Boilers -  Surveyed At LONDON in Dry Dock \_\_\_\_\_  
 (State name of Dock.) Detchers Class of Vessel & Machinery A.1. 7-91  
 Steam Pressure in Main Boilers 75 lbs (As in Register Book, including dates of Special Surveys of Ship and of last Boiler Survey.) June 12-89  
 in Donkey Boiler \_\_\_\_\_ B.S. 3-91

Last Survey No. 2-89 Port LON.

Particulars of Examination and Repairs (if any)  
 (State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?  
 Do. " Donkey " " " " "

If this was not done, state for what reasons?  
 And what parts of the Boilers could not be thus thoroughly examined?  
 Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?  
 Did the Surveyor examine the Safety Valves of the Main Boiler?  
 At what pressure were they afterwards adjusted under steam?  
 Did the Surveyor examine the Safety Valves of Donkey Boiler?  
 To what pressure were they afterwards adjusted?

*Examined stem truck, propeller, propeller fastenings and sea-cock fastenings. found same in good condition*

General Observations, Opinion, and Recommendation:— *Sofar as seen the machinery of this vessel is in good condition and eligible in my opinion to remain as classed in the Register Book.*

(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 1,91, B.&M.S. 1,91, or L.M.C. 1,91, as the case may be.)

Office or Registration Fee (per Sec. 27)	£	:	:	Fees applied for	
Survey Fee (per Section 28)	£	:	:		18
Special Damage Fee (per Section 28)	£	:	:		Received by me,
Travelling Expenses (if chargeable)	£	:	:		

*H. P. Cornish*  
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute FIL. 16 OCT 1891

Assigned As new

State if a Report is also now sent on the Ship or if not whether, and when, one will be sent.

10.-L. R. P. II.—Form No. 9.—Transfer Ink—5,000, 18/8/91  
 \*Certificate to be sent to  
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character of Ship and Machinery precisely as in the Register Book.



© 2019  
 Lloyd's Register  
 Foundation  
 LON 694-0219

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

*It is submitted  
that this vessel is eligible to remain  
AS CLASSED.*

*C. J. P.*

*15. 10. 91.*

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register  
Foundation