

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office.....)

FRI 18 MAR 1892

No. 79 Date of Writing Report 17.3.92 18 92 Port of London
 No. in Reg. Book. 79 Survey held at London Date, first Survey Feb: 21 Last Survey Mar: 11 1892
 on the Machinery of the S.S. "Paradox" Master Donkey No. of Visits 4
 Tonnage Gross 603 Net 381 Vessel built at Millwall By whom Millwall: Grang: Dr. When 1883-9
 Registered Horse Power 98 Engines made at Snla. When 1877 Boilers, when made (Main) 1885 (Donkey)
 No. of Main Boilers 1 Owners W. France & Co Port London Voyage
 Steam Pressure in Main Boilers 75 lbs. Surveyed At or in Dry Dock Fletcher Class of Vessel & Machinery 1-100 A1
 in Donkey Boiler (State name of Dock.) (As in Register Book, including dates of I.M.C. 8.89 Special Surveys of Ship and of last Boiler Survey.) B.S. 5.91
 Last Survey No. Port SS Ion: no 3-89

Particulars of Examination and Repairs (if any) Damage to Hull

(State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.)

Repairs on account of Damage should be separated from

Repairs due to other causes. State also the dates and initials of any letters respecting this case

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

Vessel placed in dry dock, sea combs: exd. found in good condn.
 Propeller disconnected, examd. found slack in after liner, a new
 Phosph. Bronze liner now fitted to former cast iron bush & propeller.
 replaced.

General Observations, Opinion, and Recommendation:— As far as seen this vessel(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 1,91, B.&M.S. 1,91, or I.M.C. 1,91, as the case may be.)appr: eligible to remain as classed.

Office or Registration Fee (per Sec. 27).....	£ :	Fees applied for
Survey Fee (per Section 28).....	£ ✓ : ✓ :	18
Special Damage Fee (per Section 28).....	£ : :	Received by me,
Travelling Expenses (if chargeable).....	£ : :	18

*State if Certificate is required

Committee's Minute TUES. 22 MAR 1892Assigned As now

Geo. E. Wiseman
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register
Foundation

LON695-0382

State if a Report is also now sent on the Ship or if not whether, and when, one will be sent.

Certificate to be sent to

18.-L. R. P. L. Form No. 3. Transmitted Feb. 6, 1892.

Insert Character of Ship and Machinery precisely as in the Register Book.

It is submitted that
this vessel is eligible to
remain AS COLASSED.

CWS

21.392

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation