

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

FRI 25 MAR 1892

No. 701 Date of Writing Report 17<sup>th</sup> March 1892 Port of London

No. in Reg. Book 701 Survey held at London Date, first Survey 10<sup>th</sup> Dec<sup>r</sup> Last Survey 10<sup>th</sup> March 1892

on the Machinery of the Ss "Genoepia" Master J. Turnbull & Co No. of Visits 15

Tonnage Gross 2069 Net 1349 Vessel built at Whitby By whom J. Turnbull & Co When 1881 9

Registered Horse Power 160 Engines made at Stockton When 1881 Boilers, when made (Main) 1881 (Donkey) 1881

No. of Main Boilers Two Owners Turner, Wrightman & Co<sup>ys</sup> Port London Voyage ✓

Steam Pressure in Main Boilers 80 lbs If Surveyed Afloat or in Dry Dock Both Class of Vessel & Machinery 100A1

in Donkey Boiler 80 (State name of Dock.) West India (As in Register Book, including dates of Special Surveys of Ship and of last Boiler Survey.) 4.91

Last Survey No. SS Npt N<sup>o</sup> 290 Port London LMC 4.90

Particulars of Examination and Repairs (if any) Damage & S.S. N<sup>o</sup> 3

(State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Do. " Donkey " " " Yes

If this was not done, state for what reasons? ✓

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

Did the Surveyor examine the Safety Valves of the Main Boiler? Yes

At what pressure were they afterwards adjusted under steam? 80 lbs

Did the Surveyor examine the Safety Valves of Donkey Boiler? Yes

To what pressure were they afterwards adjusted? 80 lbs

This vessel is reported to have stranded on the 12<sup>th</sup> of Oct. last, whilst on a voyage from Buenos Ayres to Liverpool & London, & that the machinery was severely strained. The following recommendations & repairs were made consequent on the stranding.

The vessel was placed in dry dock & main Engines opened out for inspection. Examined - Cyls, pistons, slide valves & Steam Chests found same in good order.

" Crank Shaft, found serious flaws in each Crank Pin extending round fillets, a new crank shaft has been fitted, Satis<sup>y</sup>.

" Top & bott<sup>m</sup> end brasses, found them more or less cracked & worn, the bott<sup>m</sup> end brasses & one (1) top end brass, have been renewed, Satis<sup>y</sup>.

" The main bearing brasses, found the bott<sup>m</sup> halves cracked & the top halves much worn - The four (4) bott<sup>m</sup> brasses have been renewed & the top brasses run up with white metal, & fitted to shaft, Satis<sup>y</sup>.

" Tunnel Shaft? found the same good, but the bearings were found much out - these have been run up with white metal, - Satis<sup>y</sup>.

" The tail end shaft, found the after brass very loose on the shaft, this shaft was taken to Stockton - on the after being removed a flaw was discovered in the shaft.

General Observations, Opinion, and Recommendation :-

(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey; thus, for example, B.S. 1, 91, B.&M.S. 1, 91 or L.M.C. 1, 91, as the case may be.)

The machinery of this vessel is in safe working condition & in our opinion eligible to remain as classed & to have the notification LMC 392 recorded in the Register Book of this Society.


Office or Registration Fee (per Sec. 27)	£ : :	Fees applied for	25/3/1892
Survey Fee (per Section 28)	£ 4 : 10 : -	Received by me,	2/4/1892
Special Damage Fee (per Section 28)	£ 4 : 4 : -		
Travelling Expenses (if chargeable)	£ : :		

Robert Dalpou  
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

\*State if Certificate is required

Committee's Minute TUES. 29 MAR 1892

Assigned + LMC 3, 92



State if a Report is also sent on the Ship or if not whether, and when, one will be sent.

16-1181H Form No. 9 - Printed in London, 3/1/1892.

The Surveyors are requested to state in writing on or below the space for (Classification) whether:

Insert Character of Ship and Machinery precisely as in the Register Book.

a new end was welded on, as recommended by the Society's Surveyor at that port.

Examined the Stem tube which was drawn in order to repair the damage to the stem of the vessel - the tube was found sound.

" Stem Bush found same much worn - same was re-worked.

" The Surface Condenser, found a longitudinal fracture extending about 2 ft into Steam Space - rendering the Condenser unfit for further use - A new Condenser has been fitted, Satis<sup>fy</sup>.

" All the Sea Cocks & Valves, which were in the way of the damaged strakes - these were taken off & overhauled also all their connections which were disconnected in order to repair the damage to the hull.

" All Pumps, with their valves, found same good.

" All bilge & ballast tank connections & their roses, these were all removed & overhauled & re-jointed.

" Sluice Valves which were overhauled - Satis<sup>fy</sup>.

" Ballast & Bilge pumps with their valves found same good, - the ballast driving crank shaft brasses were renewed.

" Main Steam Pipe found same good.

" Main<sup>& Aux<sup>iliary</sup></sup> Boilers, found same had shifted from their original seating - also the lagging more or less shaken off - the lagging has been renewed where necessary.

" Propeller found same in good order, - Spare one has been fitted Satis<sup>fy</sup>.

### Work not account of the Stranding.

While crossing the new crank shaft into its bearings one of the slings broke - the shaft fell on to the bed plate fracturing the same across the third bearing - rendering the bed plate unfit for further use. A new bed plate has been fitted, Satis<sup>fy</sup>.

The crank shaft was again put in turning lathe<sup>ing</sup> & trued up, Satis<sup>fy</sup> afterwards fitted into its bearings, Satis<sup>fy</sup>.

Examined Main & Aux<sup>iliary</sup> boilers & their safety valves int<sup>er</sup> & extra<sup>ly</sup> found same good.

Tested Main & Aux<sup>iliary</sup> boilers under steam & adjusted their safety lift at 80 lbs Pres. per sq. - also Eng<sup>ine</sup> satisfactorily tried under steam -

R.B. - H.P.