

Report of Survey for Repairs, &c., of Engines and Boilers.

53209

(Received at London Office. THURS. 14 JUL 1892)

No. 507 Date of Writing Report 12 July 1892 Port of London

No. of Reg. Book 507 Survey held at London Date, first Survey 27 June Last Survey 9 July 1892

on the Machinery of the Iron s/s Mount Edgecumbe Master Protheroe No. of Visits 6

Tonnage { Gross 1667 Net 1074 Vessel built at Barron By whom Barron S. B. & Co. When 1883 8

Registered Horse Power 185 Engines made at Glasgow When 1883 Boilers, when made (Main) 1883 (Donkey) 1883

No. of Main Boilers 2 Owners D. & W. D. & Co. Port Leith Voyage Zyre

Steam Pressure in Main Boilers 80 If Surveyed Afloat or in Dry Dock Union Bay St. Class of Vessel & Machinery +100 A1-690

in Donkey Boiler + (As in Register Book, including dates of Special Surveys of Ship and of last Boiler Survey.) Imc-990

Last Survey No. 88 Port London

Particulars of Examination and Repairs (if any) Damage

(State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

This vessel appears to have lost one blade of the propeller in the red sea on the 6th June 1892

The stern bush and guard ring renewed and new lignum vitae fitted, a new propeller blade fitted with new studs & the studs of remaining blades examined

The tail shaft renewed; new shaft washed

The trees bored out to fit tail shaft.

Lloyd's T.R.B. No 1366

On account of damage the main injection valve has been lowered and strake of plating.

The fastenings of sea cocks and propeller in good condition.

General Observations, Opinion, and Recommendation:— So far as seen the machinery of this vessel is now in a good and safe working condition, eligible in my opinion to remain as classed.

Office or Registration Fee (per Sec. 27).....	£ : :	Fees applied for	14/7/92
Survey Fee (per Section 28).....	£ : :	Received by me,	
Special Damage Fee (per Section 28).....	£ 4 : 4		
Travelling Expenses (if chargeable).....	£ : :		

*State if Certificate is required

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute FRI 15 JUL 1892

Assigned as above



State if a Report is also now sent on the Ship or if not whether, and when, one will be sent.

*Certificate to be sent to the Registrar of Shipping (Committee's Minute).

Insert Character of Ship and Machinery precisely as in the Register Book.

