

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

FRI 21 OCT 1892

Date of writing Report *Oct 15 92* When handed in at Local Office *is* Port of *London*.
 No. in Reg. Book. *339* Survey held at *London* Date, First Survey *Oct 11* Last Survey *Oct 13 1892*
on the Machinery of the Wood, Iron or Steel *S.S. Celtic King* Master *J. O'Boyle*
 Tonnage { Gross *3738* Net *2429* Vessel built at *Belfast* By whom *Workman, Clark & Co* When *1891* 1.
 Registered Horse Power *350* Engines made at *Glasgow* When *1891* Boilers, when made (Main) *1891* (Donkey) *1891*
 No. of Main Boilers *two* Owners *W. A. & Co.* Port *London* Voyage *New Zealand*
 Steam Pressure—*160 lbs.* If Surveyed Afloat or in Dry Dock *Royal Albert Dock* Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
 in Main Boilers *160 lbs.* (State name of Dock.)
 in Donkey Boiler *80 lbs.*

Last Survey No. *53710* Port *London*Particulars of Examination and Repairs (if any) *Safety Valves*

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " " Donkey " " " " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

If the Survey is not complete state what arrangements have been made for its completion?

Completed.
The Main Boiler Safety valves were taken adrift, examined & ground up. One spring in the port boiler was found to be weak, a new spare spring was fitted. Satis.
The Main Boilers were tested under steam, and their safety valves adjusted to lift at 160 lbs press: per sq"

General Observations, Opinion, and Recommendation:—*The Main Boiler safety valves*
 (State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey:
 thus, for example, B.S. 9, 92, B.&M.S. 9, 92 or *L.M.C. 9, 92* as the case may be.)
being now in good working order, the vessel is, in my opinion, eligible to remain as classed in the Register book

Office or Registration Fee (per Sec. 27) £ : :
 Survey Fee (per Section 28) £ : :
 Special Damage Fee (per Section 24) £ : :
 Travelling Expenses (if chargeable) £ : :
 Fees applied for
 18
 Received by me,
 18

*State if Certificate is required

Committee's Minute

TUES. 25 OCT 1892

Assigned

As now

M. Salmon.
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register
 Foundation
 LON 697-0216

It is submitted that
this vessel is able to
remain AS LASHED.

N.A.

22-10-92

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019
Lloyd's Register
Foundation