

No. 54077

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office TUES. 31 JAN 1893)

Date of writing Report 20.1.93 18 When handed in at Local Office 18 Port of London

No. in Reg. Book. Survey held at London Date, First Survey 7 Last Survey Jan 30 1893 (No. of Visits 1)

48 on the Machinery of the Wood, Iron or Steel S. S. Walton Master

Tonnage { Gross 1069 Net 688 Vessel built at Sald. By whom Short Bros. When 1877 - 1

Registered Horse Power 99 Engines made at do When 1877 Boilers, when made (Main) 1877 (Donkey)

No. of Main Boilers Owners G. L. Barton Port London Voyage

Steam Pressure in Main Boilers 70 lbs. N Surveyed Afloat or in Dry Dock Regt. (State name of Dock.)

in Donkey Boiler

Last Survey No. Port

Particulars of Examination and Repairs (if any) Condition

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

CHARACTER for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned how long.	Machinery and Boiler Surveys (including date of N.B., if any).
1-100 A1		L.M.C. 4.91
8.92		B.S. 6.92.
S.S. hwc. 1-91		

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

If the Survey is not complete state what arrangements have been made for its completion?

Vessel placed in dry dock, sea combs: etc. & found in good condtn. the propeller & its fastenings sound & the tail shaft a good fit in Stern bush.

General Observations, Opinion, and Recommendation:— As far as seen this vessel appears eligible to remain as classed.

(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 9.92, B.&M.S. 9.92 or L.M.C. 9.92, as the case may be.)


Office or Registration Fee (per Sec. 27)	£	:	:	Fees applied for
Survey Fee (per Section 28)	£	✓	✓	18
Special Damage Fee (per Section 28)	£	:	:	Received by me,
Travelling Expenses (if chargeable)	£	:	:	18

Geo. E. Wrennison  
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

\*State if Certificate is required

Committee's Minute FRI 10 FEB 1893

Assigned As now



WON 698-0114



*It is submitted that  
this vessel is eligible to  
remain AS CLASSED.*

*W.A.  
2-2-93*

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019  
Lloyd's Register  
Foundation