

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office) WED. 8 MAR 1893

Date of writing Report March 7, 1893 When handed in at Local Office London is Port of London

Survey held at London Date, First Survey Feb. 4 Last Survey March 7, 1893  
(No. of Visits Three)

71 on the Machinery of the Wood, Iron or Steel SS. DRUMMOND CASTLE Master Bryant  
Gross 2663 Vessel built at Glasgow By whom J. Elder & Co. When 1881 MONTH 2  
Net 2352 Engines made at Harlepool When 1887 Boilers, when made (Main) 1887 (Donkey) 1887

Registered 600 Owners D. Currie & Co. Port London Voyage South Africa  
Main Boilers Three If Surveyed Afloat or in Dry Dock E. India Dock & Green Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).  
Main Boilers 150lb (State name of Dock.) Dry Dock

Donkey Boiler 80lb Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Survey No. SS. n° 3 Port London

Particulars of Examination and Repairs (if any) SS. n° 3  
Medical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and details being detailed in the body of the report, should be briefly summarised at the end of the report. State also the names and initials of any letters respecting this case.

Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes  
" " Donkey " " " " Yes

was not done, state for what reasons? -

What parts of the Boilers could not be thus thoroughly examined? -

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? Yes

Did the Surveyor examine the Safety Valves of the Main Boiler? Yes  
at pressure were they afterwards adjusted under steam? 150lb. per sq"

Did the Surveyor examine the Safety Valves of Donkey Boiler? Yes  
at pressure were they afterwards adjusted? 80lb. per sq"

Survey is not complete state what arrangements have been made for its completion? Completed.

Examined Main & Donkey Boilers internally & externally & Safety Valves, all found to be in good condition, with the exception of the Donkey boiler, several of the stays in water space & the after side of the shell plating (internally) being much corroded & doubling plates three feet wide for the full length of the boiler were fitted on the after side shell plating, all the water space stays of the after combustion chamber were renewed & twenty stays of the forward combustion chamber. The boilers were afterwards seen under steam & the safety valves adjusted to the working pressures.

Examined Cylinders, Pistons, Slide valves, pumps & condenser, Crank & Trust & Tunnel shaftings, sea & bilge connections, sluices & roses, Rail and shaft drawn in & examined, all found to be in good condition with the exception of the Trust shaft which was found to be flawed, but this flaw was not considered to be of a serious nature.

General Observations, Opinion, and Recommendation: This vessel's machinery is now in good & safe condition & in my opinion the vessel is eligible to remain as classed & have notification. L.M.C. 3.93. recorded in the Register book.

Registration Fee (per Sec. 27) £ : :  
Fee (per Section 28) £ 5 10. 0.  
Damage Fee (per Section 28) £ : :  
Printing Expenses (if chargeable) £ : :  
Fees applied for 8 MAR 1893  
Received by me, J. M. Salmon  
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute TUES. 14 MAR 1893  
Signed + L.M.C. 3.93  
FRI 26 MAY 1893  
Lloyd's Register Foundation  
LON698-0230

It is submitted that  
this vessel is eligible for  
THE RECORD + LMC. 3.93

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

on account of wear & tear  
repairs of moderate  
extent have been done  
to the main boiler

Nov 8. 3.93 -

*[Faint handwritten text, likely bleed-through from the reverse side of the page. The text is mostly illegible due to fading and bleed-through.]*



© 2019  
Lloyd's Register  
Foundation