

Report of Survey for Repairs, &c., of Engines and Boilers.

THURS. 9 MAR 1893

(Received at London Office)

Date of writing Report *4th March 93* When handed in at Local Office *18* Port of *London*

No. in Reg. Book *142* Survey held at *London* Date, First Survey *27th Feb* Last Survey *1st March 1893*

on the Machinery of the Wood, Iron or Steel *S. S. Oranmore* Master *R. Bartlett*

Tonnage { Gross *3377* Net *2215* Vessel built at *Barrow* By whom *Barrow S. B. Co. (Lim.)* When *1882* Year. MONTH. *7*

Registered Horse Power *300* Engines made at *Barrow* When *1882* Boilers, when made (Main) *1882* (Donkey) *1882*

No. of Main Boilers *2* Owners *W. Johnston & Co. (Lim.)* Port *Barrow* Voyage *Boston*

Steam Pressure in Main Boilers *80* If Surveyed Afloat or in Dry Dock *Thames Dry dock Vic. St.* Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

in Donkey Boiler

Last Survey No. *100 A1* Port *Barrow*

Particulars of Examination and Repairs (if any) Condition *Surging dk. with fleeb. 10.92. S.S. Lon. 712-90*

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? *No*

Do. " Donkey " " *No*

If this was not done, state for what reasons? *Not due for survey.*

And what parts of the Boilers could not be thus thoroughly examined? *✓*

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? *No*

Did the Surveyor examine the Safety Valves of the Main Boiler? *Not adjusted*

At what pressure were they afterwards adjusted under steam? *No*

Did the Surveyor examine the Safety Valves of Donkey Boiler? *Not adjusted*

To what pressure were they afterwards adjusted? *Complete*

If the Survey is not complete state what arrangements have been made for its completion?

Vessel placed in dry dock and sea-connections. The tail end shaft and propeller being corroded at parts were now removed and a new tail shaft and propeller efficiently fitted.

General Observations, Opinion, and Recommendation:— *This vessel's machinery, so far as seen, is in safe working condition and eligible, in my opinion, to remain as classed without further record of survey.*

(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 9,92, B.&M.S. 9,92 or L.M.C. 9,92, as the case may be.)

Office or Registration Fee (per Sec. 27).....	£	:	:	Fees applied for
Survey Fee (per Section 28).....	£	:	:	18
Special Damage Fee (per Section 28).....	£	:	:	Received by me,
Travelling Expenses (if chargeable).....	£	:	:	18

*State if Certificate is required

Committee's Minute *10 MAR 1893*

Assigned *As now*

A. Elliott
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

WON 698-0248

A Report is also now sent on the Ship not whether, and when, one will be sent.

Certificate to be sent to

14-LRFB-Form No. 9-Transfer Ink-10,000, 20193.

(The Surveyor are requested not to write on or below the space for Committee's Minute.)

Insert Character of Ship and Machinery precisely as in the Register Book.

It is submitted that
this vessel is eligible to
remain AS CLASSED.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

on account of wear & tear
a new tail shaft- has
been fitted-

July 9. 3. 93-

