

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office

THURS. 30 MAR 1893)

Date of writing Report March 29 1893 When handed in at Local Office London is 18 Port of London  
No. in Reg. Book 124 Survey held at London Date, First Survey March 25 Last Survey March 29 1893  
on the Machinery of the Wood, Iron or Steel S.S. "OOPACK" Master Davies  
Tonnage Gross 2785 Net 1730 Vessel built at Glasgow By whom D.W. Henderson & Co When 1883 YEAR. MONTH. 12  
Registered Horse Power 480 Engines made at 80 When 1883 Boilers, when made (Main) 1883 (Donkey) 1883  
No. of Main Boilers 100 Owners China Mutual S.N. Co Ltd Port London Voyage China  
Steam Pressure in Main Boilers 90 lbs If Surveyed Afloat or in Dry Dock S.W. India Dock Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).  
in Donkey Boiler 90 lbs (State name of Dock.) Dry Dock

Last Survey No. B.S. 4 Port London  
Particulars of Examination and Repairs (if any) Condition  
(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes  
Do. " Donkey " " " " Yes  
If this was not done, state for what reasons? -  
And what parts of the Boilers could not be thus thoroughly examined? -  
Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? -  
Did the Surveyor examine the Safety Valves of the Main Boiler? Yes  
At what pressure were they afterwards adjusted under steam? 90 lbs per sq  
Did the Surveyor examine the Safety Valves of Donkey Boiler? Yes  
To what pressure were they afterwards adjusted? 90 lbs per sq  
If the Survey is not complete state what arrangements have been made for its completion? Completed

Examined Main & Donkey Boilers internally & externally & Safety Valves, all found to be in good condition, with the exception of the after furnace of the Donkey boiler, which was found to be badly bulged on the forward side. The bulged part was cut out & a patch about 2 feet long by 16 inches wide was effectually rivetted on. The boilers were afterwards seen under steam & the safety valves adjusted to lift at 90 lbs press. per sq.  
Examined propeller, stem bush & sea connections fastenings, all found to be in good condition.

General Observations, Opinion, and Recommendation:— This vessel's machinery is now as far as seen in good condition & in my opinion the vessel is eligible to remain as classed & have notification B.S. 3.93 recorded in the Register Book  
(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 0.02, B.&M.S. 0.02 or L.M.C. 0.02, as the case may be.)

Office or Registration Fee (per Sec. 27) £ : : Fees applied for 30 MAR 93  
Survey Fee (per Section 28) £ 2 0 0  
Special Damage Fee (per Section 28) £ : :  
Travelling Expenses (if chargeable) £ : : Received by me 6/6/93  
State if Certificate is required -  
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping. Wm Salmon

Committee's Minute TUES. 4 APR 1893  
Assigned B.S. 3.93  
Lloyd's Register Foundation  
LON 698-0328



It is submitted that  
this vessel is eligible for  
THE RECORD BS. 3.93

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

on account of wear & tear  
the after furnace of the  
doubtless boiler has been  
repaired —

20/3/93 —



© 2019

Lloyd's Register  
Foundation