

Report of Survey for Repairs, &c., of Engines and Boilers.

FRI 14 APL 1893

(Received at London Office)

Date of writing Report April 13 18 93. When handed in at Local Office London is Port of London.

No. in Reg. Book. 14 Survey held at London. Date, First Survey April 4 Last Survey April 13 1893
 on the Machinery of the Wood, Iron or Steel S.S. "NAIRNSHIRE" Master Wallace
 Tonnage Gross 3720 Net 2428 Vessel built at Newcastle By whom Hawthorn Leslie & Co. When 1889 YEAR. MONTH. 8
 Registered Horse Power 356 Engines made at Do When 1889 Boilers, when made (Main) 1889 (Donkey) 1889
 No. of Main Boilers 3 Owners Elderslie S.S. Co. L^{td} Port Glasgow Voyage Australia
 Steam Pressure in Main Boilers 160 lbs If Surveyed Afloat or in Dry Dock Brown's Dry Dock Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Survey No. Port
 Particulars of Examination and Repairs (if any) Damage.

CHARACTER. * For Special Survey, Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
<u>✠ 100 A.1.</u> <u>9.92.</u>		<u>✠ L.M.C</u> <u>8.89.</u>

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No

Do. " Donkey " " " No.

If this was not done, state for what reasons? Survey not due

And what parts of the Boilers could not be thus thoroughly examined? -

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? No

Did the Surveyor examine the Safety Valves of the Main Boiler? No

At what pressure were they afterwards adjusted under steam? No

Did the Surveyor examine the Safety Valves of Donkey Boiler? -

To what pressure were they afterwards adjusted? -

If the Survey is not complete state what arrangements have been made for its completion? Completed.

Examined propeller, stern bush & sea connections fastenings, Tail shaft drawn in & examined. Found that one propeller blade had been broken off close to the root, Tail shaft slightly bent & liners much worn, Stern bush cracked & wood gone, & neck bush worn oval; this damage was stated to have been sustained by propeller striking some hard submerged substance.

Repairs A New Blade has been fitted to the propeller, Tail shaft planed in lathe, Trued up & liners faired, new stern & neck bushes & newignum vitae strips fitted & shaft replaced, The whole being planed in as good condition as before the damage was sustained.

General Observations, Opinion, and Recommendation:— This vessels machinery is now in good condition & in my opinion the vessel is eligible to remain as classed without fresh record of survey.

Office or Registration Fee (per Sec. 27).....	£ : :	Fees applied for
Survey Fee (per Section 28).....	£ : :	<u>15/4</u> 18 <u>93</u>
Special Damage Fee (per Section 28).....	£ <u>2.2.0</u>	Received by me,
Travelling Expenses (if chargeable).....	£ : :	<u>25/4</u> 18 <u>93</u>

Wm. Salmon.
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

* State if Certificate is required.
 Committee's Minute TUES. 18 APL 1893
 Assigned As now



State if a Report is also now sent on the Ship or if not whether, and when, one will be sent.

Insert Character of Ship and Machinery precisely as in the Register Book.

It is submitted that
this vessel is eligible to
remain AS CLASSED.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

On account of damage, a
new blade fitted to the
propeller, the tail shaft
has been turned on the
lathe, & the stern tube
renursed, & new stern
& neck bushes fitted
to the stern tube.

15/4/93-

[Faint, illegible handwritten text, likely bleed-through from the reverse side of the page.]

Ernest



© 2019
Lloyd's Register
Foundation