

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office

Date of writing Report June 6 1893 When handed in at Local Office Port of London
 No. in Reg. Book. 487 Survey held at London Date, First Survey June 3 Last Survey June 3 1893
 on the Machinery of the ~~Wood, Iron or Steel~~ S.S. "ETHELBERT" Master Ling
 Tonnage { Gross 483 Net 294 Vessel built at Belfast By whom Workman Clark & Co When 1884 - 1. MONTH.
 Registered Horse Power 75 Engines made at Glasgow When 1884 Boilers, when made (Main) 1884 (Donkey) 1884
 No. of Main Boilers one Owners Ethelbert S.S. Co Ltd Port London Voyage Coasting
 Steam Pressure in Main Boilers 80 lbs If Surveyed Afloat or in Dry Dock Brodies Dry Dock Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
 in Donkey Boiler

Last Survey No. Port
Particulars of Examination and Repairs (if any) Port S. No. 3.

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time ?

Do.	"	Donkey	"	"
-----	---	--------	---	---

If this was not done, state for what reasons?

and What parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler ?

Did the Surveyor examine the Safety Valves of the Main Boiler?

at what pressure were they afterwards adjusted under steam?

Should the Surveyor examine the Safety Valves of Donkey Boiler?

Q What pressure were they afterwards adjusted to?

the Survey is not complete state what arrangements have been made for its completion?

what pressure were they afterwards adjusted?
The Survey is not complete state what arrangements have been made for its completion?
The Vessel has now proceeded to
the Tyne where the owners state they intend to carry out the Survey.
(Newcastle Surveyors have been advised)

Hammed propeller, stern bush, & sea connections fastenings.
The tail end shaft was found to be about $7/16$ " down; Recommended
tail shaft to be drawn in & stern bush rewooded, owing to the vessel
having to leave for the Lyne this has not yet been done.

General Observations, Opinion, and Recommendation:— The whole of the machinery

(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this Survey
this, for example, B.S. 2,02, B.&M.S. 2,02 or ~~X~~L.M.C. 2,02, as the case may be.)

Of this vessel is now due for Survey.

Office or Registration Fee (per Sec. 27).....	£	:	:	Fees applied for
Survey Fee (per Section 28).....	£	:	:	18
Special Damage Fee (per Section 28).....	£	:	:	
Travelling Expenses (if chargeable).....	£	:	:	Received by me,
				18

State if Certificate is required

Committee's Minute

Assigned Deferred

E. M. Salmon.
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

FRI 18 AUG 1893

Lloyd's Register
Foundation

LON699-0082

It is submitted that
this vessel is eligible to
remain AS CLASSED.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

The No 203 is due on this result —
she has proceeded to the
Tyne where this survey is
to be carried out & where
the tail shaft is to
be examined & the
stem bush rewooded —

Ref 6/6/93 —



© 2019
Lloyd's Register
Foundation