

No. 54454

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office) **FRI 23 JUN 1893**

Date of writing Report 22.6.93 18 93 When handed in at Local Office 18 Port of London

No. in Reg. Book 490 Survey held at London Date, First Survey June 10 Last Survey June 14 1893
(No. of Visits 3)

on the Machinery of the Wood, Iron or Steel S. S. "Fenwick" Master YEAR. MONTH.

Tonnage { Gross 755 Vessel built at Newcastle By whom Palmers & Co When 1866 - 2
Net 459

Registered 99 Engines made at London When 1873 Boilers, when made (Main) 1873 (Donkey)

No. of Main Boilers 1 Owners J. Fenwick & Son Port Newcastle Voyage

Steam Pressure in Main Boilers 75 lbs. & Surveyed Afloat or in Dry Dock London
(State name of Dock.)

in Donkey Boiler

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now or expired.	Machinery and Boiler Surveys (including date of N.B., if any).
<u>-1 A 1</u>		<u>B.S. 8.91</u>
<u>10.92</u>		<u>B.S. 10.92.</u>
<u>S.S. Lon: No 2-91</u>		

Last Survey No. Port
Particulars of Examination and Repairs (if any)

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

If the Survey is not complete state what arrangements have been made for its completion?

Vessel placed in dry dock, sea compass: examd: & found in good condtn:
Propeller disconnected, a new tail shaft & new gun metal bush have
now been fitted on account of wear & tear

General Observations, Opinion, and Recommendation:— As far as seen this vessel appears
(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 9,92, B.&M.S. 9,92 or L.M.C. 9,92, as the case may be.)
eligible to remain as classed.

Office or Registration Fee (per Sec. 27).....	£ : :	Fees applied for
Survey Fee (per Section 28).....	£ ✓ ✓	18
Special Damage Fee (per Section 28).....	£ :	
Travelling Expenses (if chargeable).....	£ : :	Received by me,
		18

Geo. E. Wierman
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

*State if Certificate is required

Committee's Minute TUES. 27 JUN 1893

Assigned As now



LON649-0152

14-1893-Form No. 2-1-1901-1903. (The Surveyor is requested to use in pencil on or before the space for Committee's Minute.)

It is submitted that
this vessel is classed
remain AS CLASSED

on acct of wear & tear
a new tail shaft and gunmetal
bush were fitted

M.A.
23-6-93



© 2019

Lloyd's Register
Foundation