

## Report of Survey for Repairs, &amp;c., of Engines and Boilers.

WED. 2 AUG 1893

(Received at London Office)

Date of writing Report *August 1<sup>st</sup> 93* When handed in at Local Office *18* Port of *London*  
 No. in Reg. Book. *199* Survey held at *London* Date, First Survey *July 28* Last Survey *Aug 1<sup>st</sup> 1893*  
*on the Machinery of the Wood, Iron or Steel* *S.S. "AGNES"* Master *Bretschneider*  
 Tonnage { Gross *938* Net *589* Vessel built at *Middlebrook* By whom *Backhouse & Dixon* When *1870* 2  
 Registered Horse Power *99* Engines made at *Stockton* When *1870* Boilers, when made (Main) *1879* (Donkey) *-*  
 No. of Main Boilers *two* Owners *J. Rodenacker* Port *Danzig* Voyage *Danzig*  
 Steam Pressure in Main Boilers *65 lbs* If Surveyed *Afloat or in Dry Dock* *Nelson Dry Dock*  
 Not Donkey Boiler *-*

Last Survey No. *B.S. 9* Port *Condition*  
 Particulars of Examination and Repairs (if any) *Condition*

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? *Yes*

Do. " Donkey " " *No*

*No donkey boiler fitted.*

If this was not done, state for what reasons? *-*

And what parts of the Boilers could not be thus thoroughly examined? *-*

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? *-*

Did the Surveyor examine the Safety Valves of the Main Boiler? *Yes*

At what pressure were they afterwards adjusted under steam? *65 lbs per sq*

Did the Surveyor examine the Safety Valves of Donkey Boiler? *-*

To what pressure were they afterwards adjusted? *-*

If the Survey is not complete state what arrangements have been made for its completion? *Completed.*

*Examined Main Boilers internally & externally & Safety valves also propeller, stern bush, & sea connections fastenings, all found to be in good condition. The safety valves were afterwards adjusted under steam to lift at 65 lbs pressure per sq*

General Observations, Opinion, and Recommendation:—*This vessel's boilers & machinery as far as seen are now in good condition & in my opinion the vessel is eligible to remain as classed & have record B.S. 8.93 in the Register Book*

Office or Registration Fee (per Sec. 37) £ : :  
 Survey Fee (per Section 28) £ *1. 10. 0*  
 Special Damage Fee (per Section 28) £ : :  
 Travelling Expenses (if chargeable) £ : :

Fees applied for

2/8 18 93

Received by me,

H/8 18 93

*Wm. Salmon*  
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

\*State if Certificate is required

Committee's Minute

FRI 4 AUG 1893

Assigned

*B.S. 8.93*

Lloyd's Register  
 Foundation

LON649-0363



It is submitted that  
this vessel is eligible for  
THE RECORD BS 8 93 -

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

3/8/43 -

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register  
Foundation