

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

Date of writing Report 31st July 1893 When handed in at Local Office Tilbury is Port of London

No. in Reg. Book 1005 Survey held at Tilbury Date, First Survey and Last Survey 27th July 1893
on the Machinery of the Wood, Iron or Steel S. S. "Austral" Master J. M. Tuke

Tonnage { Gross 5524 Net 3214 Vessel built at Glasgow By whom J. Eldon & Co. When 1881 Boilers, when made (Main) 1881 (Donkey) 1881

Registered Horse Power 1000 Engines made at Glasgow Owners Orient Steam Navⁿ Co. Port Glasgow Voyage Australia

No. of Main Boilers Four Steam Pressure in Main Boilers 95 If Surveyed Afloat or in Dry Dock Tilbury dry dock. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Survey No. _____ Port _____
Particulars of Examination and Repairs (if any) Condition

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No

Do. " Donkey " " " " No

If this was not done, state for what reasons? Not due for survey.

And what parts of the Boilers could not be thus thoroughly examined? No

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? Not adjusted

Did the Surveyor examine the Safety Valves of the Main Boiler? No

At what pressure were they afterwards adjusted under steam? Not adjusted

Did the Surveyor examine the Safety Valves of Donkey Boiler? Not adjusted

To what pressure were they afterwards adjusted? Complete.

If the Survey is not complete state what arrangements have been made for its completion? Complete.

Vessel placed in dry dock - sea connections, propeller & its fastenings examined & found in good order.

General Observations, Opinion, and Recommendation:— The machinery of this vessel, so far as seen, is in safe working condition, eligible, in my opinion, to remain as classed, without fresh record of survey.

	£		Fees applied for
Office or Registration Fee (per Sec. 27)			18
Survey Fee (per Section 28)			
Special Damage Fee (per Section 28)			
Travelling Expenses (if chargeable)			18
			Received by me,

A. Elliott
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

*State if Certificate is required Yes 15 AUG 1893
Committee's Minute
Assigned



State if a Report is also sent on the Ship or if not whether, and when, one will be sent.

*Certificate to be sent to
14-1434-Form No. 9—London, 20/1/93.
(The Surveyor are requested not to write on outside the space for Committee's Minute.)

Insert Character of Ship and Machinery precisely as in the Register Book.

It is submitted that
this vessel is eligible to
remain AS CLASSED.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

July 14/8/93 -

[Faint, illegible handwritten text, likely bleed-through from the reverse side of the page.]

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation