

Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report 11th Oct. 1893 When handed in at Local Office is Port of London
 in London Date, First Survey 2nd Oct. Last Survey 10th Oct. 1893
 on the Machinery of the Wood, Iron or Steel S.S. "Oranmore" Master K. Bartlett
 Gross 3377 Net 2215 Vessel built at Barrow By whom Barrow S. B. Co. When 1882 Year 7 Month 7
 Entered 300 Engines made at Do. When 1882 Boilers, when made (Main 1882 (Donkey) 1882)
 Main Boilers Two Makers W. Johnston & Co. Port Barrow Voyage Boston
 Pressure 80 Main Boilers 80 Donkey Boiler 65 If surveyed Afloat or in Dry Dock Victoria Dock. (State name of Dock.)
 Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER	Years allowed before re-examination	Machinery and Boiler Surveys (including date of N.B., if any)
<input checked="" type="checkbox"/> 100 A1. Ayring & Co. with free. 3.9/3. S.S. Lon. 7-2-90		<input checked="" type="checkbox"/> L.M.C. 8.90 B.S. 10.92.

Next Survey No. 54677 Port London.
 Particulars of Examination and Repairs (if any) B.S.
 Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and dates being detailed in the body of the report, should be briefly summarised at the end of the report. State also the initials and initials of any letters respecting this case.
 Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes.
 Do. " " Donkey " " " " No.
 Was this not done, state for what reasons? D.B. previously excd.
 What parts of the Boilers could not be thus thoroughly examined? ✓
 What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓
 Did the Surveyor examine the Safety Valves of the Main Boiler? Yes.
 At what pressure were they afterwards adjusted under steam? 80-lbs.
 Did the Surveyor examine the Safety Valves of Donkey Boiler? Yes.
 At what pressure were they afterwards adjusted? 65 lbs.
 If the Survey is not complete state what arrangements have been made for its completion? Complete -

Both Main Boilers examined internally and externally, also superheaters. Safety valves of Mm. Brs. examined and subsequently adjusted under steam to 80-lbs. Safety valves of Donkey Boiler adjusted under steam to 65 lbs.

General Observations, Opinion, and Recommendation: The machinery of this vessel, so far as seen, is in safe working condition, eligible, in my opinion, to remain as classed, with record of survey B.S. 10.93, entered in Register Book.
 (State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 9.92, B.&M.S. 9.92 or L.M.C. 9.92, as the case may be.)

Fee or Registration Fee (per Sec. 27) £ : :
 Survey Fee (per Section 28) £ 2 0 0
 Social Damage Fee (per Section 28) £ : :
 Travelling Expenses (if chargeable) £ : :
 Fees applied for 12/10/18 93
 Received by me, A. Elliott
20/10/18

A. Elliott.
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Date if Certificate is required
 Committee's Minute FRI 13 OCT 1893
 Signed B.S. 10.93



N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that
this vessel is eligible for
THE RECORD B-S-10-93

W.A.
12-10-93

000

[Faint handwritten notes and bleed-through from the reverse side of the page, including words like "business", "paper", and "order".]



© 2019
Lloyd's Register
Foundation