

# Report of Survey for Repairs, &c., of Engines and Boilers.

SAT 25 NOV 1893

Date of writing Report Nov. 24 18 93 When handed in at Local Office London is Port of London

No. in Reg. Book 125 Survey held at London Date, First Survey Oct 17 Last Survey Nov 24 18 93

on the Machinery of the Wood, Iron or Steel S.S. TIFESHIRE Master Cuthbert

Tonnage { Gross 3720 Net 2425 Vessel built at Newcastle By whom Swan & Hunter When 1887 YEAR. MONTH.

Registered Horse Power 400 Engines made at Stockton When 1887 Boilers, when made (Main) 1887 (Donkey) 1887

No. of Main Boilers 3 Owners (James Martin & Co) Port Glasgow Voyage Australia

Steam Pressure—160 lbs If Surveyed Afloat or in Dry Dock James H. & S. W. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

in Main Boilers 160 lbs (State name of Dock.) India Dock.

in Donkey Boiler 70 lbs

Last Survey No. B. S. 4 Port Condition

Particulars of Examination and Repairs (if any) Condition

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

If the Survey is not complete state what arrangements have been made for its completion?

Exam? Main & Donkey Boilers internally & externally & safety valves, also propeller, Stern Bush & Sea connections fastenings, all found to be in good condition.

The Boilers were afterwards seen under steam & the safety valves were adjusted to lift at their respective working pressures.

General Observations, Opinion, and Recommendation:—This vessel's Boilers are now in good condition & in my opinion the vessel is eligible to remain as classed & have record B.S. 11.93. in the Register book.

Office or Registration Fee (per Sec. 27) £ : : Survey Fee (per Section 28) £ 2 : 10 : 0 Special Damage Fee (per Section 28) £ : : Travelling Expenses (if chargeable) £ : :

Fees applied for 25.11.93 Received by me, 16/11 18 94

Mr. Salmon  
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

\*State if Certificate is required

Committee's Minute TUES. 28 NOV 1893

Assigned B.S. 11.93

State if a Report is also new sent on the Ship or if not whether, and when, one will be sent.

\*Certificate to be sent to

16-LRPH—Form No. 9—Transfer 1893—10,000, 20/1/93.



*It is submitted that  
this vessel is eligible for  
THE RECORD BS 11.93 -*

*Prob  
25/11/93 -*

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register  
Foundation