

Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report 19th Dec: 1893 When handed in at Local Office Port of London (Received at London Office DEC 20 1893)
 No. in Reg. Book Survey held at London Date, First Survey 7th Dec. Last Survey 19th Dec. 1893
447 on the Machinery of the Wood, Iron or Steel S.S. Dunottar Castle Master J.C. Robinson
 Tonnage { Gross 5465 Net 3069 Vessel built at Glasgow By whom Fairfield Co. (Lim.) When 1890 Boilers, when made (Main) 1890 (Donkey) 1890
 Registered Horse Power 1100 Engines made at Do. When 1890 Boilers, when made (Main) 1890 (Donkey) 1890
 No. of Main Boilers Four Owners D. Currie & Co. Port London Voyage Cape
 Steam Pressure in Main Boilers 160 If Surveyed Afloat or in Dry Dock Thames I. Wks. drydk. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
 in Donkey Boiler 160 (State name of Dock.)

Last Survey No. _____ Port _____
 Particulars of Examination and Repairs (if any) Condition

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

CHARACTER for Special Survey, Date of last Survey and of Periodical Surveys.	Years Assigned or expired.	Machinery and Boiler Surveys (including date of N.B., if any).
<u>100 A 1. Spark. 9. 93.</u>		<u>L.M.C. 8. 90.</u>

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No
 Do. " Donkey " " " " No
 If this was not done, state for what reasons? Not due for survey.
 And what parts of the Boilers could not be thus thoroughly examined? ✓
 Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓
 Did the Surveyor examine the Safety Valves of the Main Boiler? No
 At what pressure were they afterwards adjusted under steam? Not adjusted
 Did the Surveyor examine the Safety Valves of Donkey Boiler? No
 To what pressure were they afterwards adjusted? Not adjusted


If the Survey is not complete state what arrangements have been made for its completion? Complete.
Sea-connections, propeller & its fastenings examined in dry dock and found in good order.
The H.P. Cylinder has now been re-bored and made 5/16" larger - the cylinder being now 38 5/16" which should be noted in the Register Book.

General Observations, Opinion, and Recommendation:— The machinery of this vessel, so far as seen, is in safe working condition, eligible, in my opinion, to remain as classed without further record of survey.

Office or Registration Fee (per Sec. 27).....	£	:	:	Fees applied for
Survey Fee (per Section 28).....	£	:	:	
Special Damage Fee (per Section 28).....	£	:	:	
Travelling Expenses (if chargeable).....	£	:	:	

R. Elliott
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

*State if Certificate is required _____
 Committee's Minute FRI 23 DEC 1893
 Assigned As now
Note dir. of Cy.



Stat is also now sent on ship...
 16-LEAF—Form No. 9—Transfer Ink—10/600, 20/130.
 *Certificates to be sent to...
 If the Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character of Ship and Machinery precisely as in the Register Book.

It is submitted that
this vessel is eligible
remain AS CLASSED.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

For reasons not stated, the High
Pressure cylinder has been
rebored & made $\frac{5}{16}$ " larger in
dia. The dia of this
cylinder is now $38\frac{5}{16}$ " which
should be noted in
the Reg. Book —

Sub
20/12/93 —



© 2019

Lloyd's Register
Foundation