

FRI 23 FEB 1894

(Received at London Office

Date of writing Report *Feb. 22* 18*94* When handed in at Local Office *18* Port of *London.*  
 No. in Survey held at *London.* Date, First Survey *Feb. 12* Last Survey *Feb. 21.* 18*94*  
 Reg. Book. *64.* on the Machinery of the ~~Wood, Iron or Steel~~ *S.S. "ELCHUCA"* Master *Bond.* (No. of Visits *5.*)  
 Tonnage { Gross *2826* Vessel built at *Middlebrook* By whom *A. Dixon & Co.* When *1889* YEAR. MONTH. *1*  
 { Net *1736* Engines made at *Hartlepool.* When *1889* Boilers, when made (Main) *1889* (Donkey) *1889*  
 Registered Horse Power *400* Owners *W. Lund.* Port *London* Voyage *Sydney.*  
 No. of Main Boilers *3*  
 Steam Pressure—*150 lbs* If Surveyed ~~Afloat or~~ in Dry Dock *Greens Dry Dock* Particulars of Classification (which must be inserted  
 in Main Boilers *✓* (State name of Dock.) *Paplar.* precisely as in Register Book & Supplements).  
 in Donkey Boiler *✓*

*Last Survey No.*.....*Port*.....

Particulars of Examination and Repairs (if any) Condition

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time ?

Do.	„	Donkey	„	„	„
-----	---	--------	---	---	---

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined ?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler ?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted ?

If the Survey is not complete state what arrangements have been made for its completion?

Examined propeller, stern bush & sea connection fastenings, tail end  
shap-drawn in & examined. Found wood in stern bush worn down  
& bush slack in tube.  
A new stern bush has now been fitted, the stern tube being bored out  
to suit.

General Observations, Opinion, and Recommendation:—This vessel's machinery is now as  
(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey:  
thus, for example, B.S. 2,92, B.&M.S. 2,92 or ~~X~~L.M.C. 2,92, as the case may be.)  
for as seen in good condition & in my opinion the vessel is eligible to remain  
as classed without fresh record of survey.

Office or Registration Fee ( <i>per Sec. 27</i> )	£	:	:	Fees applied for
				18
Survey Fee ( <i>per Section 28</i> )	£	:	:	
Special Damage Fee ( <i>per Section 28</i> )	£	:	:	Received by me,
Travelling Expenses (if chargeable)	£	:	:	18

\* State if Certificate is required.

### Committee's Minute

*Assigned*

TUES. 27 FEB 1894

*P. M. Salmon.*  
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

© 2019

Lloyd's Register  
Foundation

CON701-0259

State if a Report is also now sent on the Ship  
or if not whether, and when, one will be sent.

*\*Certificate to be sent to—  
see's Minute.)*

200, 2/10/93.

16--LRPH--KCM No. 6 Tr.

—



R. 8.  
23/2/94



Lloyd's Register  
Foundation