

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report. 30/7/1894 When handed in at Local Office. 30/7/1894 Port of London

No. in Reg. Book. Survey held at London  
71 on the Wood Iron or Steel & S. Nutilus

Date, First Survey 2-7-94 Last Survey 27 July 1894

(No. of Visits) 15

Master Dyman

YEAR.

MONTH.

TONNAGE:-  
GROSS 718  
UNDER D.K. 636  
NET 467

Built at Sunderland and By whom G. & G. Gullston  
Owner General Steam & Co.

Port belonging to London

When 1874 11

Owners' Address  
(if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock Slipway Name of Dock Nelson Slipway Destined Voyage Rotterdam

WB=DB ~~abc~~ 55 ft. fine 45 feet; uE&B tons; CellDB tons;  
FPT tons; APT tons; MT tons;

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER:  
 for Special Survey  
Date of last Survey and of Periodical Surveys

Years assigned  
Machinery and Boiler Surveys (including date of N.B., if any).

+ QOA.1. Linc. 5/93  
7/93  
Sl. Pen No. 33/84  
London Nov. 2/93  
Society's Freeboard (if assigned) as painted on Ship and now verified 2 ft. 2 1/2 ins.

N.B.—All alterations in the existing records should be underlined.

Last Survey, No. 5573 Port Lon

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawser is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage Repairs.

In consequence of damage sustained to the bows by striking a pole in the River Maas in October last and by collision with the ss "Avocet" of Liverpool and a lighter in January at Rotterdam, also for damage to Bulwarks and Counter de Thro' a collision with a Dutch Government Sailing Cruiser, the "Nautilus" in the North Sea in June. This steamer was placed on the patent slipway at Nelson Dock, the bottom examined, cleaned & recoated.

On the port bow four plates were renewed 10. 22. 18  
29. & Two plates faired in place v. 22, 37, and  
one plate 72 removed faired and replaced.

SUMMARY OF DAMAGE REPAIRS:— 12 Plates, Fairied or Repaired; 7 Plates, Renewed; 2 Frames, ditto. Other Repairs Repair to bulwark Counter bridge th. to

PRESENT CONDITION OF THE Decks

Good

Transoms, Pointers, & Catches

Good

Copper, or Y.M.

(State if now fitted)  
When put on, Month

Year

Hatches

Good

Boats

Masts, Yards, &c.

Condition, how ascertained

from the

Sails

Equipment letter

A

Anchors, No. of

313-18-215

Cables (State if now ranged)

no

Length

Rule length

size

Size

Standing & Running Rigging

Good

one plate in G strake fairing in place & strengthened by a doubling plate between the frames. part of No 5 frame cut out & renewed. & a new reverse bar fitted to same. Several rivets cut out of plates in the E & F strakes and indents in same heated & fairing in place. One frame tie was fitted in fore peak  $6 \times 16 \frac{1}{3}$  on the starboard bow. - Nos 8. Nos 9 & cut out & renewed and three plates adjacent to same heated and fairing in place, a bosom cover fitted and riveted to No 1 frame.

on the port side in way of bridge, one bulwark plate just before the bridge and another within the bridge cut out & renewed. Three <sup>bulw</sup> plates adjacent to same fairing in place. Four plates in the upper course of bridge berthing cut out and renewed, and two plates adjacent heated & fairing in place, the angle irons on top of same renewed, also berthing plates in round above end of bridge forming ramps and 5 beams renewed of bridge deck. One plate at fore end of bridge bulkhead renewed & the adjacent plate removed fairing and replaced.

on the starboard side of bridge dk. one plate in round above end of bridge renewed and one plate in the berthing below, also one plate in front of bridge. and two beams.

on the port side of Raised Q dk. Three bulwark plates were renewed, two others removed fairing and replaced and two more fairing in place. 70 feet of angle iron rail renewed & 45 feet of berthing (top gall) angle iron rails renewed at stern, & 100 feet gallant berthing <sup>beams</sup> wood rails renewed. Two freeing ports refitted twelve bulwark stays repaired & refitted.

on the starboard side of R.Q dk aft at stern  
Two plates of bulwarks cut out & renewed  
Six counter bulwark plates removed & renewed & adjacent plates fairing in place, 53 feet of rail angle renewed, & 43 feet of top gallant berthing angles together with plate berthing renewed. one stringer plate and R.Q sheer strake plate of mild steel angle cut out & renewed, also wood rails, one freeing port <sup>Concluded</sup> bulwark stanchions

S/S "Nautilus"

The fore bridge renewed together with the stays  
handrails, cloths &c. The iron scrauchers ~~had~~  
no t rails &c at front of bridge renewed, the ladder  
side light screens, compass pole & repaired & replaced

About 120 feet of Bridge dk planking 3"x6" pine renewed  
on the port side together with 18 feet of waterway.

The bunker hatch coamings re bolted, new hatch  
fitted, & the boats, chocks, wheel chains, blocks &  
overhauled made good on each side. on the starb  
side about 10 feet of water <sup>way</sup> 20 feet of deck was renewed.

About 180 feet of 3"x6" pitch pine deck on port side of R Q dk  
as counter was renewed together with 14 feet of waterway.  
The damaged wood rails were renewed on each side  
where necessary together with fittings attached  
thereto.

The port hatches were repaired and a new oak carling  
fitted to same. 3 chain plates refitted to the  
main rigging, 1 new mooring pipe fitted &

The cabin linings &c aft were repaired & replaced  
one bollard refitted. the companion to cabin  
renewed, the cabin & at front of bridge  
rebuilt & refitted. rigging repaired

The funnel removed, repaired & replaced and  
the foley casing &c repaired. & a number  
of sundry other minor repairs effected.

Edward J. Tierney