

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report.	29/11/94	When handed in at Local Office.	29/11/94	Port of London.		
No. in Reg. Book.	Survey held at London.		Date, First Survey	5/11/94	Last Survey	23/11/1894
			(No. of Visits)	16		
316	on the Wood, Iron on Steel S.S. "Glenmanna."		Master	Courtman	YEAR.	MONTH.
TONNAGE:-	Built at	T.Y. Shields	By whom	Smith	When	1871
GROSS	Owners	Sollas & Sons	Port belonging to			Newcastle
UNDER DK.	Owners' Address	(if not already recorded in Appendix to Register Book.)				
NET	Surveyed Afloat or in Dry Dock?	Ways	Name of Dock	Southwark	Destined Voyage	Goole
W.R.-D.Ba	tons; f.	tons; u.E&B	tons; CellDB	tons;	Particulars of Classification which must be inserted	

FPT	tons; APT	tons; MT	tons.	
<u>N.B.—All alterations in the existing records should be underlined.</u>				
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.				
Last Survey, No.	55877	Port	Low	
(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment should be clearly stated, and the date and initials of any letters respecting this case.)				

REPAIRS OR EXAMINATION AS PER RULE FOB Damaged Repairs

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage Repairs
in consequence of colliding with the S.S. Ethelbert whilst swinging
off Goole Docks doing damage to stern on October 11th 1894; also
for damage caused by striking a buoy and colliding with the
steamer S.S. Consent in the River Ouse on Nov 2nd 1894.
This steamer was placed on Mountain ways, the bottom
examined as far as practicable.

Repairs to stern, 3 plates on the rounded plating of stern renewed, 2 plates of tick of stern removed faired or replaced, 2 others renewed. 5 stern frames repaired 2 lengths of moulding renewed, 2 pieces of wood waterway of poop deck renewed. 5 stanchions repaired and refitted and rails replaced. Steering standard, blocks &c refitted cement, linings & cabin fittings replaced

SUMMARY OF DAMAGE REPAIRS : Plates, Fair'd or Repaired ; Frames, ditto. Plates, Renewed ; Frames, ditto. Other Repairs... Rudder repaired

General Observations, Opinion as to Class, Recommendation, &c. :—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—".....to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."

This steamer now appears to be in a sound and efficient condition, eligible in my opinion to re-entering as classed with a fresh record of survey

Low 11/19/14

Office Fee (if chargeable) per Scale II., Sec. 27 £ : : Fees applied for,
28. 1. 84.

Survey Fee (per Section 28) £ 4 : 4 : 0 29/1/1894

Special Damage or Repair Fee (if any) £ : Received by me,
Edward J. H. Service
per Sec. 28.
1898

Travelling Expenses (if chargeable) £ : / : 18. Surveyor to Lloyd's Register of British & Foreign Shipping.

*Is Certificate now required? FRIDAY 30 NOV 1894 © 2019 Committee's Minutes

Committee's Minute
Chairman un-named

Character assigned
Lloyd's Reg

Digitized by the Internet Archive Foundation

Lent 103

Digitized by srujanika@gmail.com

'Glenmanna'

The Rudder was unshipped and placed on shore and the plates removed, fairing and refitted. The bow of the rudder having been previously fairing and the broken part welded; the lower fork pindle repaired and refitted, the rudder re-shipped and two new wheel chains fitted.

The damage to the port side forward, abaft fore peak bulkhead, one sheer strake renewed, also two plates in the next strake below, and two others in the same strake removed fairing & replaced three plates in the 2nd strake below sheer fairing in way of upper landing edge, 97 frames fairing, repaired &c. 3 bulwark plates renewed, 1 wash or fanning refitted, with open hinges, 26 feet angle iron rail renewed, & 56 feet of oak main rail & 32 feet of top gallant rail & berthing; the clocks at end of forecastle forming ramp renewed coaming to Tr.C at end of forecastle renewed, 1 plank in scle deck renewed, 2 chain plate removed, repaired and replaced, four bulwark stays repaired, 2 side scuttles in scle repaired & sundry other repairs of minor importance.

Edward H. Turner