

Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report *Nov 30* 18*94* When handed in at Local Office *Port of London* 18*94*
 No. in Reg. Book. *299* Survey held at *London* Date, First Survey *Oct. 15* Last Survey *Nov. 29* 18*94*
 on the Machinery of the *Wood, Iron or Steel* *S.S. ITUNI* Master *Smith*
 Tonnage { Gross *2226* Net *779* Vessel built at *Newcastle* By whom *W. Richardson & Co.* When *1884* Year. Month. *6*
 Registered Horse Power *726* Engines made at *Do* When *1884* Boilers, when made (Main) *1884* (Donkey) *1884*
 No. of Main Boilers *2* Owners *Demerara & Bertha S.S. Co.* Port *London* Voyage *West Indies*
 No. of Donkey Boilers *2* If Surveyed Afloat or in Dry Dock *Bridge Dry Dock & East India Dock* Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
 Steam Pressure— in Main Boilers *90 lbs* in Donkey Boilers *50 lbs*

Last Survey No. *100 A-1-2-94* Port *L.M.C.*
 Particulars of Examination and Repairs (if any) *Damage & London*
 (Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? *No*
 Do. " Donkey " " " *No*
 If this was not done, state for what reasons? *Survey not due*
 And what parts of the Boilers could not be thus thoroughly examined?
 Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? *No*
 Did the Surveyor examine the Safety Valves of the Main Boiler? *No*
 At what pressure were they afterwards adjusted under steam? *No*
 Did the Surveyor examine the Safety Valves of Donkey Boiler? *No*
 To what pressure were they afterwards adjusted? *Completed*
 If the Survey is not complete state what arrangements have been made for its completion?

Tail end shaft drawn in & examined & stem bush rewooded
Found L.P. front column broken just before top flange. This damage was sustained during heavy weather on Oct. 14 1894.
A new column has now been fitted.

General Observations, Opinion, and Recommendation:— *This vessel's Machinery is now as far as seen in good condition & in my opinion the vessel is eligible to remain as classed.*

Office or Registration Fee (per Sec. 27) £ : : Fees applied for *11/2 1894*
 Survey Fee (per Section 28) £ : : *Received by me*
 Special Damage Fee (per Section 28) £ *1* : *1* : *0*
 Travelling Expenses (if chargeable) £ : : *4/11 1895*

*State if Certificate is required
 Committee's Minute *TUES. 4 DEC 1894*
 Assigned *As now*
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

Lon 703 - 0435

On acct of damage
a new Column was fitted to the engine

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that
this vessel is eligible to
remain AS CLASSED.

N.A.
1-12-94

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation