

REPORT of SURVEY for REPAIRS, &c.

Writing Report 15th Jan 1895 When handed in at Local Office.

Jan 1895 Port of London

Survey held at London Date, First Survey Dec 13 Last Survey Jan'y 9th 1895

(No. of Visits)

Master 6 H. Smith

YEAR. MONTH.

on the Wood, Iron or Steel sc. Bn "Symbeline"

TONNAGE 1394 Tons

DSS 1209

DER DK 1170

T 1170

Built at Stockton

By whom Richardson Duck & Son When 1849

Owners Thompson Elliott & Co.

Port belonging to Hull.

Owners' Address

(If not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Afloat + Name of Dock Canal Dry Dock Destined Voyage

B= DBa 46 tons; f 62 tons; uE&B tons; CellDB tons; FPT tons; APT tons; MT tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides be tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, etc., and of the inner bottom plating, especially in the boiler space.

1st Survey, No. 10437 Port of

Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the use of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the placement of Anchors, Chains, or Hawser is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment tier, if any. State also the dates and initials of any letters respecting this case.

PAIRS, OR EXAMINATION AS PER RULE, FOR Repairs on account of damage through collision grounding at Bilbao

Now done:—The stem renewed, & the following shell plates on the starb' bow renewed viz: N° 1+2 in A stroke, N° 1 in B stroke, N° 1+2 in C stroke, N° 1 in D stroke, N° 1 in E stroke, N° 1 in F stroke, N° 1 in G stroke, N° 1 in H stroke, N° 1+2 in I stroke, N° 1 in K stroke, N° 1+2 in L stroke, N° 1 in M stroke, with the hawse pipe doubling plate attached to it, and on the port bow, plate N° 1 in A+B strokes, N° 1+2 in C stroke, N° 1 in D, E, F & G strokes, N° 1+2 in H+I strokes, and N° 1 in K+L strokes. The foremost frame with reversed frame on each bow renewed, N° 1 floor renewed, frame N° 2 with its reversed frame renewed on Starb' bow, fore end of lower deck stinger renewed & lower deck strings part renewed, tricell hooks refitted, several shell chocks renewed, hawse pipe refitted woodlass overhauled forecastle deck & fore end of main deck recaulked, fore peak cleared, caulking of collision bulkhead

SUMMARY OF DAMAGE REPAIRS — Plates, Fair'd or Repaired; Frames, ditto. Metal Plates, Renewed; Frames, ditto. Other Repairs Stem new, one floor &c.

PRESENT CONDITION OF THE

Decks	Good	Transoms, Pointers, & Crutches	not seen	Copper, or T.M.	Good	Hatches	Good
Waterways		Timbers of Frame at the openings	Good	(State if on Felt.)		Boats	"
Seamings	"	Ditto ditto at other places		When put on, Month		Masts, Yards, &c.	"
Drk. Beams & Fastenings	"	Kelsons	Good	Rudder	Good	Condition, how ascertained	from DK
Drk. Beams & Fastenings	"	Clamps, Shells & Stringers	Good	Windlass & Capstan	"	Sails	Suff.
Salting		(State if examined.)		Pumps	"	Equipment letter	P
Ceiling		Cement or Asphalt		Engine Room Skylights	"	Anchors, No. of	3 Br. 1 Sm + 2 Kgs
Ancaking	✓	(State which.)		Coal Bunker, Open'g, Lids, &c.	"	Cables (State if now ranged)	
Seamants or Rivets	"	Tanks	✓	Scuppers	"	" length	size
Fasthocks & Stemson	"	(State if now tested.)	Good	Cargo & Main H'tehw'y's	"	" Rule length	size
		Caulking of Bot'm, Drk, & Wat'rwy's				Hawsers & Warps	
						Standing & Running Rigging	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"..... to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9/91," or "to remain as classed and to have record of survey, 9/91, and the notations of ss No. 1-91 and ptND91, &c."

This vessel is now so far as seen in good condition and in my opinion eligible to remain as classed & when the tanks have been cleaned out & cement in bottom examined as arranged to have record of survey 1-95 in the Register Book.

Fees (if chargeable) per Scale II, Sec. 27 £ : : :

Fees applied for,

Survey Fee (per Section 28) £ : : :

22/11 1895

FRI 18 SEP 1896

pecial Damage or Repair Fee (if any) £ : : -

6 : 6 : -

Received by me,

FRI JUN 12 1896

Traveling Expenses (if chargeable) £ : : -

less 10% 6 : 6 : -

16/12 1895

FRI DEC 27 1896

Second Surveyor's Fee (if any) £ : : :

P.G.C.J.

C. Buchanan FRI 30 OCT 1896

Is Certificate now required?

19

Surveyor to Lloyd's Register of British & Foreign Shipping.

TUES. 8 OCT 1896

Committee's Minute

FRI 25 JAN 1895

Character assigned

Deferred for

H.S.

£51.95 compl. of Dry 95 survey.

1/1/96

© 2010 Lloyd's Register Foundation



No. 1 dues

THE BRITANNIA

56148 Jan.

overhauled & collision bulkhead tested by filling
fore peak with water to load water line,
one length of bilge keel on port side renewed.

The bottom examined in dry dock & found to
have sustained no damage with the exception of
the broken length of bilge keel now renewed.

Part of the iron ore cargo being on board at the
time of this survey it was arranged with the
Superintendent Engineer that the tanks should
be cleaned out & cement in bottom examined at
the earliest opportunity.

C Buchanan.