

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 18 When handed in at Local Office 18 Port of London

No. in Reg. Book Survey held at London Date, First Survey January 16 Last Survey February 21 1895 (No. of Visits 20) Master Winkler

450 on the Wood, Iron or Steel S.S. Blue Bell Built at Port Glasgow By whom J. J. Dunlop & Co. When 1892 5

TONNAGE:- GROSS 562 UNDER DEK 118 NET 344 Owners (Lawer, Sons & Oakley) Port belonging to London

Surveyed Afloat or in Dry Dock? D.D.K. Name of Dock Commercial D.D.K. Destined Voyage Antwerp

WB=DBa tons; f tons; uE&B tons; Cell DB tons; FPT tons; APT tons; MT tons. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined. If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Survey, No. 55912 Port Lon

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage Repairs

in consequence of a collision with the sailing barge 'Charles Pearson' doing damage to starb. bow on Aug 9<sup>th</sup> 1894 and for collision with the S.S. Emily on Sept 7<sup>th</sup> 1894 doing damage to stem & plating on the starboard bow while in the River Thames, on Oct 12<sup>th</sup> 1894 it was stated the vessel struck a barge with her port bow, bending some plates; & on Oct 25<sup>th</sup> 1894 in consequence of stress of weather carried away steam steering gear; on Jan 3<sup>rd</sup> 1895 broke window during a gale off Flushing, on Jan 7<sup>th</sup> 1895 grounded in Limehouse Reach at 2.40pm & came off at 5.15 pm. &c.

This steamer was placed in Commercial Dry Dock at Rotherhithe, the bottom examined, cleaned & recoated.

SUMMARY OF DAMAGE REPAIRS: 158 Plates, Faired or Repaired; 36 Frames, ditto. ✓ Plates, Renewed; ✓ Frames, ditto. Other Repairs: Current up, Rail bar out, ruptured, adol. Kelson fitted under main hatch.	PRESENT CONDITION OF THE	Transoms, Pointers, & Gratches	Copper, or Y.M. (State if on Plate) When put on, Month	Hatches
Boats	Good	Timbers of Frame at the openings	Year	Boats
Waterways	Good	Ditto ditto at other places	Good	Masts, Yards, &c.
Keelsons	Good	Keelsons	Good	Condition, how ascertained
Up'r Dk. Beams & Fastenings	Good	Clamps, Shells & Stringers	Good	Sails
Low'r Dk. Beams & Fastenings	Good	Setting (State if examined.)	Good	Equipment letter
Plating	Good	Ceiling	Good	Anchors, No. of 3 B, 18, 2 R
Rivets	Good	Cement or Asphalt (State if on Plate)	Good	Cables (State if now ranged) (only pair) no length size
Breasthooks & Stoppers	Good	Tanks (State if now tested.)	Good	Standing & Running Rigging
		Caulking of Bot'm, D'k, & Wat'rw'ys	Good	

### General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."

This steamer now appears to be in a sound and efficient condition, eligible in my opinion to remain as classed with a fresh record of survey Lon 2/95

Office Fee (if chargeable) per Scale II, Sec. 27 £ Survey Fee (per Section 29) £ Special Damage of Report (per Sec. 29) £ 10 : 10 : 0 Travelling Expenses (if chargeable) £ 1 : 1 : 0 Less 10% Second Surveyor's Fee (if any) £ 9 : 9 : 0

Received by me, Edward J. Tierney, Surveyor to Lloyd's Register of British & Foreign Shipping. Qu. W. Cooper

Blue Bell 215

## Damage Repairs (contd)

All the loose ceiling in fore main holds removed, the Engine Room & stokehold flooring lifted, the Ballast tank in after hold opened out, the cement examined all fore & aft, the after hold tank & fore peak tank tested with water after the repairs had been effected, the ceiling relaid & repaired where necessary.

One length of keel under main hatchway removed straightened & replaced, the fore & after ends of the adjoining pieces of keel faired in place.

Eight garboard plates removed four on each side of keel faired and replaced.

From the stoke hold bulkhead forward to mast, 30 frames were unripped from A to C staves, & the plating faired in position, 23 additional frames were fitted on frames No 30 to 52 inclusive, from Bilge to Bilge & the original frames lined up with thick liners all the wash plates on each side of middle line from floors 21 to 52 were removed, & an intercostal keel on fitted in lieu of same, which was attached to the shell plating & extended above the floors to receive a bulb plate & double angle irons.

A number of defective & started rivets in the shell plating in flat of bottom & keel were renewed.

The steam steering gear & chains were overhauled three cleats on Bulwark renewed, 1 bulwark stanchion repaired on port side aft. A new cast iron side to windlass was fitted & windlass overhauled Seven plates were taken off the bows, which were faired and replaced. viz: on port side 5 plates No 2 and No 4 in F, No 2 in E, No 1 in D and C. on the starb<sup>d</sup> side No 2 in E & No 3 in F & the plates adjacent faired in place (6 in No), the frames in way of these plates faired in place & lined up where necessary. viz: on starb<sup>d</sup> side Nos 7, 11, 13 & Nos 7, 10 & 13 on port side. The starboard

Hawse pipe was removed, the doubling plate taken off & faired; the plate behind faired in place, & the wood work in way of same replaced

On the starboard side, the stem plates in B, E & F, staves were faired in place.

near rig.

The rudder was lifted & pintles rebushed, there were a number of minor repairs also effected

Edward J. D. Jones  
G. P. Corbin