

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report March 1st 1895 When handed in at Local Office March 4th 1895 Port of London

No. in Reg. Book. Survey held at London Date, First Survey 1st Feby 95 Last Survey 27th Feby 1895
 309 on the Wood, Iron or Steel S.S. Glenmannia Master Courtnance
 TONNAGE:— Built at North Shields By whom Smith
 GROSS 738 Owners Sollas & Sons. Port belonging to London
 UNDER D.K. 650
 NET 473
 Surveyed Afloat or in Dry Dock? afloat Name of Dock Regent Canal Destined Voyage Goole

WB= DBa tons; f tons; uE&B tons; CellDB tons;
 FPT tons; APT tons; MT tons.

N.B.—All alterations in the existing records should be underlined.
 If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Survey, No. 56075 Port London

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chaine, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage Repairs

in consequence of a collision with the fish carrier ss Eastwood in the Lower Hope and the ss River Lagan off Regents Canal Dock on Saturday February 9th 1895 whilst on a voyage from Goole to London.

This steamer was seen afloat in Regent Canal Dock, on the port bow nos or stern plate in upper course of forecastle berthing renewed nos plate had its fore end faired in place. In the lower stroke of forecastle berthing nos plate renewed and no 2 plate faired in place. On the sheer stroke nos plate renewed no 2 faired in place. In first stroke below sheer nos plate renewed no 2 faired in place at fore end. In second stroke below sheer nos faired in place in several places. about 30 feet of half round iron mouldings renewed. Five frames repaired nos. upper part

SUMMARY OF DAMAGE REPAIRS:— 8 Plates, Fairing or Repaired; 8 Frames, ditto. 7 Plates, Renewed; 7 Frames, ditto. Other Repairs. *Steel strings fairing plates renewed. port bulwarks repaired*

PRESENT CONDITION OF THE		Doubling Plates under Sounding Pipes	not seen	
Decks	Good	Transoms, Fenders, & Catches	Good	Copper, or P.M. (State if now fitted.) When put on, Month Year
Waterways	"	Timbers of Frame at the openings	"	Rudder
Coamings	"	Ditto ditto at other places	"	Windlass & Capstan
Up'r Dk. Beams & Fastenings	"	Keelsons	"	Pumps
Low'r Dk. Beams & Fastenings	"	Chains, Spikes & Stringers	"	Engine Room Skylights
Plating	"	Siding (State if examined.)	"	Coal Bunker, Open'gs, Lids, &c.
Planking	"	Ceiling	"	Scuppers
Freshairs & Rivets	"	Cement or Asphalt (State if now tested.)	"	Cargo & Main H'tch'ys
Breasthooks & Stanchions	"	Tanks (State if now tested.)	"	Hatches
		Gaulking of Bot'm, D'k, & Wat'r'ys	"	Boats
				Masts, Yards, &c.
				Condition, how ascertained
				Sails
				Equipment letter
				Anchors, No. of 33—18—21
				Cables (State if now ranged). 200
				length Rule length size
				state complete
				Hawsers & Warps
				Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."

This steamer now appears to be in good condition, eligible in my opinion to remain as classed subject however to the vessel being submitted for inspection in a dry dock at the earliest opportunity. I suggest that record of survey be made in the Register Book.

Office Fee (if chargeable) per Scale II, Sec. 27 £ : : Fees applied for, £ : :
 Survey Fee (per Section 28) £ : : 18...
 Special Damage or Repair (see if any) (per Sec. 28) £ : : Received by me, £ : :
 Travelling Expenses (if chargeable) £ : : 18...
 Second Surveyor's Fee (if any) £ : :
 *Is Certificate now required?

Committee's Minute
 Character assigned

Edward J. Deverey
 Surveyor to Lloyd's Register of British & Foreign Shipping.

FRIDAY 22 MAR 1895 © 2019

FRIDAY 8 MAR 1895

90A1

subject to Dryd



Lloyd's Register
 Foundation
 LON704-0381012

S. S. Glenmarae.

partly renewed, lower portion set fair in place, and a bosom piece fitted over fracture. nos 2 upper part renewed, lower portion faired in place, no 3 frame faired in place, a new revera fitted for a length of 6 feet, and a bosom piece over fracture nos 4 & 5 frames heated and faired in place.

on the starboard bow:- In upper course of forecastle berthing nos plate renewed, nos 2 plate faired in place. In lower stroke of file berthing nos 1 plate renewed. In sheer stroke, nos 1 plate renewed, nos 2 plate faired in place. In stroke below sheer nos 1 plate faired in place on upper edge. About 25 feet of half round iron mouldings renewed. Three frames repaired nos 1 frame being partly renewed & the lower part faired in place nos 2 & 3 faired in place. nos 3 repaired with a bosom cover over fracture.

The upper part of the stem renewed for a length of 10' 3" and the old stem in way of scarph faired in place. The hawse pipes removed and refitted with new wood chocks. The wood waterway each side removed & renewed for a length of 5 feet.

The main deck caulked across for a distance of 12 feet from stem about 17 strokes of forecastle deck planking renewed abt. 250 ft and deck caulked: Two anchor fish davits, one on each side removed & replaced. Deck casting to ditto on port side refitted also sockets to receive heels of these davits. Two lengths of waterway renewed and the hand rails & stanchions refitted as before. Two gunwale angles renewed one on each side one file deck stringer plate renewed on port side, and one plate faired in place. one forecastle beam renewed.

on the port side the bulwarks were repaired. 1 plate being removed faired & replaced & 2 plates faired in place. Three freeing ports repaired, also five bulwark stanchions removed repaired & refitted. The cement in waterway repaired also where disturbed in fore peak.

When the vessel had discharged her cargo, the stem was examined and it was found that the stem & the adjacent plating had sustained some injury in the neighbourhood of the 10 feet water mark, which was temporarily made good for the voyage. As the vessel was urgently required the owners have agreed to place the vessel in dry dock, or upon a gridiron for inspection and repairs on her return to London.

Edward J. Surveyor

© 2019