

FRIDAY 18 MARCH 1895

No. 56286

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report. 6<sup>th</sup> MAR. 1895 When handed in at Local Office.

18 Port of London

No. in Reg. Book. Survey held at London.

Date, First Survey 22<sup>nd</sup> Feb. Last Survey 22<sup>nd</sup> Feb. 1895.  
(No. of Visits)

120 on the Wood, Iron or Steel S.S. "Admiral"

Master Oakley

YEAR MONTH.

## TONNAGE:-

GROSS 2392

UNDEE Dk. 1814

NET 1532

Built at W. Hartlepool By whom Mr. Gray &amp; C. When 1893 6

Owners General Steam Nav. Co. Port belonging to London

## Owners' Address

(if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Name of Dock In the River Destined Voyage

WB=DAa tons; f tons; uE&amp;B tons; CellDB tons; FPT tons; APT tons; MT tons.

Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements).

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

CHARACTER.		Machinery and Boiler Surveys (including date of N.B., if any).
for Special Survey. Date of last Survey and of Periodical Surveys.	+100A 1. 12.93. drift	

Last Survey, No. 9538 Port Ml

Society's Freeboard (if assigned) as painted on Ship and now verified 1 ft. 10<sup>1</sup>/<sub>2</sub> ins.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawser is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &amp;c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

## REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion of Equipment and Examination of Repairs to Standard Quarter

The Master stated that the two bow anchor and one length of chain cable required to complete equipment had been placed on board but no certificates for these were produced.

One of these anchors was examined and the marks on same found to be "16742. L.P.H.T. 5.94. weight 40.0.24 Rule wt. 40 cwt. Length 35' 18" 3" 0"

The other anchor was hauled up into the house pipe & the marks on same could not be ascertained.

The length of chain cable was examined & found to be 1<sup>13</sup>/<sub>16</sub> dia and numbered "4.5. - 14955". Rule size 1<sup>13</sup>/<sub>16</sub>

It was stated that the steel wire & hemp hawsers twists required to complete the equipment were on the Company's

## SUMMARY OF DAMAGE REPAIRS :— Plates, Fair'd or Repaired ; Frames, ditto. Plates, Renewed ; Frames, ditto. Other Repairs.

## PRESENT CONDITION OF THE Doubling Plates under Sounding Pipes

Decks	Good	Transoms, Pointers, & Crutches	Not seen	Copper, or Y.M.	—	Hatches	Good
Watervays	"	Timbers of Frame at the openings	Good	(State if on Felt.)		Boats	"
Coamings	"	Ditto ditto at other places	Not seen	When put on, Month	Year	Masts, Yards, &c.	"
Up'r Dk. Beams & Fastenings	"	Keelsons	Part seen Good	Rudder	Part seen Good	Condition, how ascertained	From DR
Low'r Dk. Beams & Fastenings	"	Clamps, Shelves & Stringers	"	Windlass & Capstan	"	Sails	
Plating	Part seen	Salting	(State if examined.)	Pumps	"	Equipment letter	5
Planking	"	Ceiling	" "	Engine Room Skylights	"	Anchors, No. of	3B. 15. 2K
Treenails or Rivets	"	Cement or Asphalt	(State which.)	Coal Bunker, Open'gs, Lids, &c.	"	Cables (State if now ranged)	2
Breasthooks & Scrimmons	Not seen	Tanks	(State if now tested.)	Scuppers	"	" length	size
		Caulking of Bot'm, Dk, & Wat'rwy's	Good	Cargo & Main H'tohw'y's	"	" Rule length	size
						Hawsers & Warps	Good
						Standing & Running Rigging	"

## General Observations, Opinion as to Class, Recommendation, &amp;c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"..... to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."

This vessel as far as seen, is now in good and efficient condition and eligible in my opinion to remain as classed without fresh record subject to the equipment being completed and the certificates of new anchors & chains being produced for examination & comparison.

Office Fee (if chargeable) per Scale II, Sec. 27 £

Fees applied for,

Survey Fee (per Section 28) £

18

Special Damage or Repair Fee (if any) £

Received by me,

Travelling Expenses (if chargeable) £

18

Second Surveyor's Fee (if any) £

Is a Certificate now required?

TUES 12 MAR 1895

TUES 19 MAR 1895

TUES. 10 SEP 1895

Committee's Minute

Character assigned

Deferred

Wm. O. Deverell

J. 12. 3. 95.

E. B. Chappell

Surveyor to Lloyd's Register of British &amp; Foreign Shipping.

2019


 Lloyd's Register  
Foundation  
HON704 0388 (Gr2)

Port of

London

Continuation of Report No. 56286 dated

FRIDAY 8 MAR 1935  
on the

S.S "Adjutant"

premises at Deptford and would be placed on board  
at the first opportunity.

Repairs of damage to Starboard quarter:- It is  
stated that these repairs had been carried out at  
the Company's works at Deptford & that one plate in  
upper strake of poop side plating had been cut out  
fair'd and refitted and that there was no damage to  
the frames in way of same. The vessel was lined  
in the poop in way of this repair & the frames could  
not be examined.

E&G Hampshire