

## Report of Survey for Repairs, &amp;c., of Engines and Boilers.

Date of writing Report Aug 20 1895 When handed in at Local Office 18 Port of London (Received at London Office. WED 21 AUG 1895)No. in Reg. Book 128 Survey held at London Date, First Survey June 15 Last Survey Aug 20 1895 (No. of visits 5)on the Machinery of the Wood, Iron or Steel S.S. TIFESHIRE Master WilsonTonnage { Gross 3720 Net 2425 Vessel built at Newcastle By whom Swan Hunter When 1887. 7.Registered 429 Horse Power 400 Engines made at Stockton When  Boilers, when made (Main) (Donkey)No. of Main Boilers 3 Owners (Jumbuk Martin & Co) Port Glasgow Voyage AustraliaNo. of Donkey Boilers 1 If Surveyed Afloat or in Dry Dock  Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).Steam Pressure 160 lbs in Main Boilers 160 lbs in Donkey Boilers 75 lbs Last Survey No.  Port  Particulars of Examination and Repairs (if any) Comp of S.S.

Periodical Surveys, when held, must be reported in detail and serialim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? YesDo. " Donkey " " " NoIf this was not done, state for what reasons? Already examined see Lada report No 56072And what parts of the Boilers could not be thus thoroughly examined? Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? Did the Surveyor examine the Safety Valves of the Main Boiler? YesAt what pressure were they afterwards adjusted under steam? 160 lbsDid the Surveyor examine the Safety Valves of Donkey Boiler? NoAt what pressure were they afterwards adjusted? 75 lbsHas the propeller shaft been drawn and examined at this time? NoIf the Survey is not complete state what arrangements have been made for its completion? CompletedExamined Main Boilers internally & externally & Safety valves, also.propeller & sea connection fastenings, all found to be in good condition.All the Safety valves were adjusted under steam.General Observations, Opinion, and Recommendation:— This vessel's Boilers and Machinery  
(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 4, 94, B.&M.S. 4, 94 or L.M.C. 4, 94, 150 lb., F.D., &c.)  
as far as sea are now in good condition & in our opinion the vessel is eligible  
for record B.S. 11. 94. as recommended in the Lada report No 56072.Office or Registration Fee (per Sec. 27)..... £ : :  
Survey Fee (per Section 28)..... £ 2 : 10 : 0  
Special Damage Fee (per Section 28)..... £ 2 : 5 : 0  
Travelling Expenses (if chargeable)..... £ 2 : 5 : 0Fees applied for  
21/8/95  
Received by me  
28/8/95

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute FRI. 23 AUG 1895TUES. 3 SEP 1895FRI. JAN 31 1896FRI. FEB 21 1896FRI. MAY 29 1896Assigned B.S. 11. 94Lloyd's Register  
Foundation

LON 706-0225



It is submitted that  
this vessel is eligible for  
THE RECORD B.S. 11.94.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

*22. 8. 95.*

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register  
Foundation