

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

WED, 28 AUG 1895

Date of writing Report Aug 28 18 95 When handed in at Local Office Port of London

No. in Reg. Book. 387 Survey held at London Date, First Survey August 21 Last Survey Aug 27th 1895

on the Machinery of the Wood, Iron or Steel S.S. TITANIC Master Hanslip

Tonnage Gross 1668 Net 1076 Vessel built at Belfast By whom M. Moine Lewis & Co. Ltd When 1888 YEAR. MONTH. 5

Registered Horse Power 180 Engines made at Do When 1888 Boilers, when made (Main) 1888 (Donkey) 1888

No. of Main Boilers 2 Owners Carr, Pringle, Clapperton & Co. Mgrs. Port Belfast Voyage West Indies

No. of Donkey Boilers 1 If Surveyed Afloat or in Dry Dock S.W. India Dry Dock Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Steam Pressure in Main Boilers 160 lbs in Donkey Boilers 60 lbs

Last Survey No. PortParticulars of Examination and Repairs (if any) B.S. Condition

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? YesDo. " Donkey " " " YesIf this was not done, state for what reasons? ✓And what parts of the Boilers could not be thus thoroughly examined? ✓Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓Did the Surveyor examine the Safety Valves of the Main Boiler? YesAt what pressure were they afterwards adjusted under steam? 160 lbs.Did the Surveyor examine the Safety Valves of Donkey Boiler? YesTo what pressure were they afterwards adjusted? 50 lbs.Has the propeller shaft been drawn and examined at this time? No.If the Survey is not complete state what arrangements have been made for its completion? Completed.

Examined Main & Donkey Boilers internally & externally and safety valves also propeller and sea connections fastenings. All found to be in good condition.

Safety valves all adjusted under steam.

General Observations, Opinion, and Recommendation:— This vessel's Boilers & Machinery

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 4,04, B.&M.S. 4,04 or L.M.C. 4,04, 140 lb., F.D., &c.)

are now as far as sea in good condition & in our opinion the vessel is eligible for record B.S. 8.95.

Office or Registration Fee (per Sec. 27)..... £ : :
 Survey Fee (per Section 28)..... £ 2 : 0 : 0
 Special Damage Fee (per Section 28)..... Less 10% £ : 4 : 0
 Travelling Expenses (if chargeable)..... £ 1 : 16 : 0

Fees applied for

29/8/1895

Received by me,

5/9/1895

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute

TUES, 3 SEP 1895

Assigned



© 2019

Lloyd's Register
Foundation

LON 706-0282

It is submitted that
this vessel is eligible for
THE RECORD 13. 8. 95.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to shew through to the other side.

Ed
29. 8. 95.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation