

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

MON. 14 OCT 1895

Date of writing Report *8 Oct 1895* When handed in at Local Office *8 Oct 1895* Port of *LONDON*
 No. in Reg. Book. *15* Survey held at *LONDON* Date, First Survey *20 Sept 1895* Last Survey *7 April 1895*
 on the Machinery of the *Wood, Iron or Steel* *S.S. "Paradox"* Master *J. Gilder*
 Tonnage Gross *574* Net *366* Vessel built at *LONDON* By whom *Mellor & Co.* When *1873* YEAR. MONTH.
 Registered Horse Power *98* Engines made at *Ad* When *'83* Boilers, when made (Main) *'83* (Donkey) *'83*
 No. of Main Boilers *1* Owners *H. France & Co* Port *LONDON* Voyage *Goole*
 No. of Donkey Boilers *1* If Surveyed Afloat or in Dry Dock *Afloat in Green Bay Dock*
 Steam Pressure in Main Boilers *75 lbs* (State name of Dock.)
 in Donkey Boilers *50*

Last Survey No. *15* Port *LONDON*Particulars of Examination and Repairs (if any) *Damage to Propeller*

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside Main Boiler separately and make a thorough examination at this time? *yes*Do. " Donkey " " " *yes*If this was not done, state for what reasons? *yes*And what parts of the Boilers could not be thus thoroughly examined? *yes*Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? *yes*Did the Surveyor examine the Safety Valves of the Main Boiler? *yes*At what pressure were they afterwards adjusted under steam? *72 lbs*Did the Surveyor examine the Safety Valves of Donkey Boiler? *yes*To what pressure were they afterwards adjusted? *55 lbs*Has the propeller shaft been drawn and examined at this time? *yes*If the Survey is not complete state what arrangements have been made for its completion? *Survey complete*

No damage repairs made account of the vessel grounding on the 14 September 1895 in voyage Goole to London. A new Propeller and Propeller Shaft and Stern-bush fitted all Sea connections overhauled.

As ordinary repairs an efficient patch put on outer side of the condenser about one hundred new condenser tubes fitted. Cylinders and Piston examined and found in good order.

Main Boiler examined. Mid Furnace found defective. One weak part rivet cut out and a riveted patch put on. Higher casing done to shell bottom seams and a riveted patch renewed after these repairs this Boiler tested to 110 lbs by water pressure and no signs of any weakness seen.

Donkey Boiler examined and found generally in fair order. Holes drilled in firebox shell and thickness taken was under 7/16. A new man door now fitted to this Boiler.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 4,04, B.&M.S. 4,04 or L.M.C. 4,04, 110 lb., F.D., &c.)

The Machinery of this vessel is now in good order and in my opinion eligible to remain as classed with fresh record of 18.9.95

Office or Registration Fee (per Sec. 27) £ *1 10*
 Survey Fee (per Section 28) £ *1 10*
 Special Damage Fee (per Section 28) £ *0 3 0*
 Travelling Expenses (if chargeable) £ *1 7 0*

Fees applied for

12 10 18 95

Received by me

23/10/95

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

State if Certificate is required

TUES. 15 OCT 1895

Committee's Minute

Assigned *BS 10.95*

© 2019

Lloyd's Register Foundation

Screw & screw shaft renewed owing
to damage
Moderate repairs to engines & boiler
owing to wear & tear

It is submitted that
this vessel is eligible for
THE RECORD 13. 10. 95.

R.S.
14. 10. 95.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation