

No. 57054

Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report *26th Oct 1895* When handed in at Local Office *28th Oct 1895* Port of *LONDON* (Received at London Office *WED 30 OCT 1895*)
 No. in Reg. Book. Survey held at *LONDON* Date, First Survey *14th Oct 1895* Last Survey *23rd Oct 1895*
 on the Machinery of the *Wood, Iron or Steel* *S.S. Gresham Castle* Master *A. Kendall*
 Tonnage { Gross *346 0* Net *238 7* Vessel built at *Glasgow* By whom *J. Sedgwick* When *1880* YEAR. MONTH. *12*
 Registered Horse Power *575* Engines made at *"* When *80* Boilers, when made (Main) *80* (Donkey) *88*
 No. of Main Boilers *2* Owners *J. Currie & Co.* Port *LONDON* Voyage *E of Good Hope*
 No. of Donkey Boilers *1*
 Steam Pressure in Main Boilers *150* If Surveyed Afloat or in Dry Dock *afloat in S. Sea Dock* Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
 in Donkey Boilers *80*

Last Survey No. _____ Port _____
 Particulars of Examination and Repairs (if any) *Annual Boiler Survey £101 11 7 95*
 (Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)
 £ L.M.C. *6 92*
 £ N.B. *2 88*
 £ B.S. *9 44*

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? *yes*
 Do. " Donkey " " " *yes*
 If this was not done, state for what reasons? _____
 And what parts of the Boilers could not be thus thoroughly examined? _____
 Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? _____
 Did the Surveyor examine the Safety Valves of the Main Boiler? *yes*
 At what pressure were they afterwards adjusted under steam? *157 lbs*
 Did the Surveyor examine the Safety Valves of Donkey Boiler? *yes*
 At what pressure were they afterwards adjusted? *80 lbs*
 Was the propeller shaft drawn and examined at this time? *no*
 If the Survey is not complete state what arrangements have been made for its completion? *Survey complete.*

None done. Main Boilers examined and found to be generally in good condition. Safety valves have been adjusted under steam as above.
Donkey Boiler examined. Slight corrosion observed in the stays in lower parts of combustion chamber, but these are still in satisfactory condition. Holes now drilled in the lower plating of combustion chamber, and the thinnest parts found are still 3/8" in thickness.

General Observations, Opinion, and Recommendation:—
 (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 4, 94, B.&M.S. 4, 94 or L.M.C. 4, 94, 10 lb., &c.)
The Boilers of this vessel are in satisfactory condition and in my opinion eligible to remain as classed with fresh record of B.S. 10 95.

Office or Registration Fee (per Sec. 27) £ : :
 Survey Fee (per Section 28) £ *2 10/- less 10% = 2 5*
 Special Damage Fee (per Section 28) £ : :
 Travelling Expenses (if chargeable) £ : :
 Fees applied for *30/10/1895*
 Received by me, *J. Ritchie*
 State if Certificate is required *yes* FRI. 1 NOV 1895
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute _____
 Assigned *22 10 95*
 © 2019 Lloyd's Register Foundation LON 707-0050

*It is submitted that
this vessel is eligible for
THE RECORD.*

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

B. S. 10. 95.

*Ans.
30. 10. 95*

[Faint, illegible handwritten text in cursive script, likely bleed-through from the reverse side of the page.]

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation