

Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report 2nd Jan 1895 When handed in at Local Office 4 Jan 1895 Port of London
No. in Reg. Book 389 Survey held at London Date, First Survey 30 Dec 1894 Last Survey 20 Feb 1895
on the Machinery of the Wood, Iron or Steel T.S. Thomas & Co. Master L. Sear
Tonnage Gross 4046 Net 2606 Vessel built at Glasgow By whom Barclay Curle & Co. When 1891
Registered Horse Power 479 Engines made at " When '91 Boilers, when made (Main) '91 (Donkey) '91
No. of Main Boilers 1 Owners D. Currie & Co. Port London Voyage C of Genl & Co.
No. of Donkey Boilers 1
Steam Pressure 160 lb If Surveyed Afloat or in Dry Dock at Green's Dry Dock Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Survey No. Port
Particulars of Examination and Repairs (if any) While in dry dock 10th 11 94
(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?
Do. " Donkey " " "
If this was not done, state for what reasons?
And what parts of the Boilers could not be thus thoroughly examined?
Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?
Did the Surveyor examine the Safety Valves of the Main Boiler?
At what pressure were they afterwards adjusted under steam?
Did the Surveyor examine the Safety Valves of Donkey Boiler?
To what pressure were they afterwards adjusted?
Has the propeller shaft been drawn and examined at this time?
If the Survey is not complete state what arrangements have been made for its completion?
No. Survey complete!
Known: Propeller, Stern-bush, and outside fastenings of sea connections examined and found in good condition.

General Observations, Opinion, and Recommendation:—
(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 4,04, B.M.S. 4,04 or S.L.M.C. 4,04, 140 lb., F.D., &c.)
The machinery of this vessel is in good condition and in my opinion eligible to remain as classed without fresh record.

Office or Registration Fee (per Sec. 27) £ : : Fees applied for 18
Survey Fee (per Section 28) £ : :
Special Damage Fee (per Section 28) £ : :
Travelling Expenses (if chargeable) £ : :
Received by me, D. Currie
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.
*State if Certificate is required No.
Committee's Minute FRI. 8 NOV 1895
Assigned as now.

State if a Report is also now sent on the Ship or if not whether, and when, one will be sent.

16-1895-Report No. 9-Transfer Ink-5,000, 3/4 95.
The Surveyors are requested not to write on or below the space for Committee's Minute.

It is submitted that
this vessel is eligible to
remain AS CLASSED.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

[Signature]

6. 11. 95.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation