

~~REPORT of SURVEY for REPAIRS, &c.~~

Writing Report. 25th Nov 1895 When handed in at Local Office. 18. Port of London

Survey held at London

on the Wood, Iron or Steel Ship "Ptarmigan"

Date, First Survey 5th Nov 1895 Last Survey 20th Nov 1895

(No. of Visits) 15

Master Salmon

YEAR.

MONTH.

TONNAGE:— Built at Dundee

By whom Gourlay Bros & Co When 1891

Gross 780

Owners General Steam Nav Co

Port belonging to London

Net 672

Owners' Address

(if not already recorded in Appendix to Register Book.)

Voyaged Afloat or in Dry Dock? Name of Dock Nelson Dvel.

Destined Voyage Country

Cell DB or DBa

tons; uE&B tons; f tons; t

FPT tons; APT tons; MT tons. }

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, &c., and of the inner bottom plating, especially in the boiler space.

1st Survey, No. 1959 Port Rot

CHARACTER.
X for Special Survey.
Date of last Survey and of Periodical Surveys.

Years Assigned now expired.
Machinery and Boiler Surveys
(Including date of N.B., if any).

X 100AI

1.95

X FIMC 1951

Society's Freeboard (if assigned) as painted on Ship and now verified 1 5 1/2 ins.

AIRS, OR EXAMINATION AS PER RULE, FOR

88 No 1 and Damage repairs

All the requirements of the special survey have now been completed. Inside of vessel cleaned & cleaned down all fore & aft in work in holds, turn aeks, peaks, & bunkers, examined & found good. Machinery bogs examined. Tanks examined internally & found & run good; afterwards tested satisfactory to deck level. Pumps, shins, WT doors, & equipment generally, all good. Mast & rigging examined along; all now good.

Vessel bottom examined in dry dock. It is now in good condition & has been cleaned & coated. Rudder has been reboxed.

Damages Port bow was struck in collision last voyage by 88 "Ocean". Two plates of Feil shin, one of strake below & one of main shin

ART OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Other Items:—
Renewed	8 ✓	3 ✓	✓	✓		
Faired or Repaired ...	4 ✓	30 ✓	20 ✓	✓	4 ✓	

CONDITON OF THE	Timbers of Frame at the openings	good	Rudder	good	Hatches	good
	Ditto ditto at other places	"	Windlass & Capstan	"	Boats	"
	Keelsons	"	Pumps	"	Masts, Yards, &c.	"
	Clamps, Shels & Stringers	"	Sluice Valves	"	Condition, how ascertained	from Dr.
	Salting	"	Watertight Doors	"	(State if wedges removed)	no
	(State if examined.)		Dblng. Plates under Sounding Pipes	"	Sails	good
	Ceiling	"	Engine Room Skylights	"	Equipment letter	m
	Cement or Asphalt	"	Coal Bunker, Open'gs, Lids, &c.	"	Anchors, No. of	3 B 1 S 1 K
	(State which.)		Scuppers	"	Cables (State if now ranged)	no
	Tanks	"	Cargo & Main H'tch'w'y's	"	" length	size
	(State if now tested.)	yes			" Rule length	size
	Caulking of Bot'm, D'k, & Wat'rwy's	"			Hawsers & Warps	good
	Copper, or Y.M.	"			Standing & Running Rigging	"
	(State if on Felt.)					
	When put on, Month	Year				

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon his survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9.91," or "to remain as classed and to have record of survey, 9.91, and the notations of ss No. 1-91 and ptND91, &c."

This vessel is now in good & efficient condition & is eligible in my opinion to remain as classed with record of survey 11.95 & the datum 8.8. from No 1-95.

(if chargeable) per Scale II, Sec. 27 £

Fees applied for,

£ 3 : 10 : 0

28.11. 1895

£ 0 : 7 : 0

Received by me,

£ 3 : 3 : -

6/12/95

£ 0 : 1 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£ 0 : 0 : -

18/12/95

£

21/10/38 has referred to 5/1/39 Lon

broken all four plates now renewed. Three frames renewed at this part and eleven faired in place. Fore beam ends renewed, and one stringer plate of forecastle deck renewed.

Forecastle deck (wood) partly renewed & recaulked.

The fore mast was swept down by the collision; the plate badly buckled has been renewed, another slightly bent has been faired. Plates cut adrift & mast apparent repaired. Fore stay renewed.

Damage through impingements with quarry walls incurred at various times, chiefly in Manchester canal. One plate starboard side, fore end of fore hold, 1st station below sheer taken off & fairied. Six frames in way of same found in place.

Ammanship Port side. One plate in first below sheer & two in 2^d below sheer badly buckled have been renewed. One plate in 2^d below sheer taken off & fairied. Twelve frames at this part, faired in place.

Fore end of fore hold, Port side. One plate 2^d below sheer taken off & fairied. Plate below fairied in place & one frame fairied in place.

Starboard side of Poop. One plate of Poop sheer, which had been temporarily patched has been renewed. Also gammon bar & cope iron renewed at this part.

A number of rivets in lacunae eyes of bilge strake here & there on both sides found started, have been renewed. About 250 Keel rivets found slack have been renewed.