

# No. 57159

## Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report	20 Nov 1895	When handed in at Local Office	21 Dec 1895	(Received at London Office)	WED. 4 DEC 1895
No. in Reg. Book.	Survey held at London.		Port of London		
219	on the Machinery of the Wood, Iron or Steel		S.S. "Mara"	Master	L. C. Buttress
Tonnage	Gross 14478	Net 927	Vessel built at Newcastle	By whom Palmer's Co.	YEAR. MONTH.
Registered Horse Power	1400	No. of Main Boilers 2	Engines made at "	When 1883	
No. of Donkey Boilers 1	Steam Pressure— in Main Boilers 50 lbs	If Surveyed Afloat or in Dry Dock (State name of Dock.)	Boilers, when made (Main) 83 (Donkey) 83	Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).	
in Donkey Boilers 60			Port London. Voyage London		

Last Survey No. Port

Particulars of Examination and Repairs (if any) Boiler Survey

*(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the date and initials of any letters respecting this case.)*

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? *yes.*

Do. " Donkey "

If this was not done, state for what reasons? *Latter at work.*

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

Has the propeller shaft been drawn and examined at this time?

If the Survey is not complete state what arrangements have been made for its completion?

*Not done for annual River Survey; Main Boilers examined in every part and found to be generally in satisfactory condition for the above Working Pressure.*

*A draught Map, which has been repaired has, it is stated now been put on board this vessel as spare. Please see Letter attached herewith.*

### General Observations, Opinion, and Recommendation:

*(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 2,92, B.M.S. 4,92 or L.M.C. 4,92, 140 I.B. F.D., &c.)*

*The Machinery of this vessel is in good condition and, in my opinion eligible remaining afloat with full load of 13.5 when the Donkey Boiler is examined. copy of letter to owners attached.*

Office or Registration Fee (per Sec. 27)	£ 2 . . .	Fees applied for	4/12/1895	H.W.
Survey Fee (per Section 28)	£ 2 . . .			
Special Damage Fee (per Section 29)	£ 0 . 4 0			
Travelling Expenses (if chargeable)	£ 1 . 1 6 0	Received by me,	29/11 1895	

*D. Rennie*  
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

\*State if Certificate is required.

Committee's Minute

FRI. 6 DEC 1895

TUES. MAR 3 1896

FRI. MAY 22 1896  
FRI. 18 SEP 1896

Assigned

*Deferred*

© 2019



Lloyd's Register  
London 0211