

# Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report 18th May 96 18. When handed in at Local Office London 18. Port of London (Received at London Office WED. MAY 20 1896)

No. in Reg. Book 128 Survey held at London Date, First Survey Apr 29 Last Survey 14th May 1896

on the Machinery of the Wood Iron or Steel S. S. Fishery Master Wilson

Tonnage { Gross 3428 Net 2425 Vessel built at Newcastle By whom C. I. Swan & Hunter When 1887 YEAR. MONTH.

Registered Horse Power 429 Engines made at Stockton When 1887 Boilers, when made (Main) 1887 (Donkey) 1887

No. of Main Boilers Three Owners Turnbull, Martin & Co. Port Glasgow Voyage Australia

No. of Donkey Boilers one If Surveyed Afloat + in Dry Dock Vic. Dk. & Thames Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Survey No. \_\_\_\_\_ Port \_\_\_\_\_

Particulars of Examination and Repairs (if any) S. S. No 2

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Do. " Donkey " " " Yes

If this was not done, state for what reasons? \_\_\_\_\_

And what parts of the Boilers could not be thus thoroughly examined? \_\_\_\_\_

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? Yes

Did the Surveyor examine the Safety Valves of the Main Boiler? Yes

At what pressure were they afterwards adjusted under steam? 160 lbs

Did the Surveyor examine the Safety Valves of Donkey Boiler? Yes

To what pressure were they afterwards adjusted? 74 lbs

Has the propeller shaft been drawn and examined at this time? Yes. renewed -

If the Survey is not complete state what arrangements have been made for its completion? Complete

Now done. — All cylinders, pistons, slide valves, pumps, condenser main, thrust & tunnel shafting examined. The Main & Donkey boilers examined, also their safety valves and the latter adjusted under steam. The propeller shaft was drawn & examined & found to be corroded at the forward end of the after liner & the after liner slack. This shaft has now been removed & the spare one (new) fitted. All sea & bilge cocks & valves examined. Repairs stated to be due to damage caused through grounding off Oamaru during last voyage — L. P. & I. P. piston rods bent were now taken out and faired. Damage survey made by M<sup>r</sup>. Lewis, Underwriters surveyor.

General Observations, Opinion, and Recommendation: — This vessel's machinery is now in safe working condition and eligible, in my opinion, to remain as classed with record of survey L.M.C. 5.96 entered in the Register Book

Office or Registration Fee (per Sec. 27) £ \_\_\_\_\_  
Survey Fee (per Section 28) £ 5.10.0  
Special Damage Fee (per Section 28) £ 4.19.0  
Travelling Expenses (if chargeable) £ \_\_\_\_\_

Fees applied for 27 May 1896  
Received by me 11/11/96  
R. Elliott  
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute FRI, MAY 29 1896  
+ L.M.C. 5.96  
FRI 11 DEC 1896

Assigned \_\_\_\_\_



Certificate to be sent to...  
If so, is the Report sent now, or when will it be sent?  
If a Survey has been held on Ship?  
Lloyd's Register of British and Foreign Shipping

Screw shaft renewed owing to damage.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that  
this vessel is eligible for  
THE RECORD + L. h. C. 5. 96.

J. L. S.

27. 5. 96.

*[Faint, illegible handwritten text, likely bleed-through from the reverse side of the page.]*

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2020

Lloyd's Register  
Foundation