

# Report of Survey for Repairs, &c., of Engines and Boilers.

TUES. JUN 16 1896

Date of writing Report 13<sup>th</sup> June 1896 When handed in at Local Office 15<sup>th</sup> June 1896 Port of London

No. in Reg. Book 7 Survey held at London Date, First Survey 8 Last Survey 17<sup>th</sup> June 1896

on the Machinery of the Wood, Iron or Steel S. S. Pacia Master D. Gordon

Tonnage Gross 1856 Net 1473 Vessel built at Sunderland By whom J. Laming When 1867. 11.  
Registered Horse Power 207 Engines made at (Comp) When 75 Boilers, when made (Main) 75 (Donkey)  
No. of Main Boilers 2 Owners W. & T. G. & Co. Ltd Port London Voyage Not Fixed  
No. of Donkey Boilers 1  
Steam Pressure in Main Boilers 70 If Surveyed Afloat or in Dry Dock in a Dry Dock Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Survey No. \_\_\_\_\_ Port \_\_\_\_\_

Particulars of Examination and Repairs (if any) Stern-bush + BA 1. 10. 95  
S. J. L. 103. 1. 93 Lucy. 1. 93 BS. 10. 95

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?  
Do. " Donkey " " " "

If this was not done, state for what reasons? \_\_\_\_\_

And what parts of the Boilers could not be thus thoroughly examined? \_\_\_\_\_

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? \_\_\_\_\_

Did the Surveyor examine the Safety Valves of the Main Boiler? \_\_\_\_\_

At what pressure were they afterwards adjusted under steam? \_\_\_\_\_

Did the Surveyor examine the Safety Valves of Donkey Boiler? \_\_\_\_\_

To what pressure were they afterwards adjusted? \_\_\_\_\_

Has the propeller shaft been drawn and examined at this time? yes.

If the Survey is not complete state what arrangements have been made for its completion? Complete.

Now done! Tail shaft drawn in and examined and found good. New wood fitted in Stern-bush. Fostering of sea connections in good order. Propeller also examined and found good.

See Lim. List

### General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,95, B.&M.S. 9,95 or L. M.C. 9,95, 140 lb., F.D., &c.)  
The machinery of this vessel is in good condition and, in my opinion, eligible to remain as classed. Without fresh record the vessel has been removed from Special Limitation List.

	£	s	d	Fees applied for
Office or Registration Fee (per Sec. 27)				18
Survey Fee (per Section 28)				
Special Damage Fee (per Section 28)				
Travelling Expenses (if chargeable)				18
Received by me,				

D. Ritchie  
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

\*State if Certificate is required \_\_\_\_\_

Committee's Minute FRI. JUN 19 1896

Assigned as now

but without limit



Due to wear & tear. Stem bark rewooded.

It is submitted that  
this vessel is eligible to  
remain AS CLASSED.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

Vessel's name to be removed from Limitation  
List

From  
17.696

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2020

Lloyd's Register  
Foundation