

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office. THUR 6 AUG 1896)

Date of writing Report 4th August 96 When handed in at Local Office London is London Port of London

No. in Reg. Book 292 Survey held at London Date, First Survey and Last Survey 31st July 1896

on the Machinery of the Wood, Iron or Steel S. S. "Thermopylae" Master A. Simpson

Tonnage { Gross 3711 Net 2396 Vessel built at Aberdeen By whom Hall, Russell & Co. When 1891 11

Registered Horse Power 415 Engines made at Do. When 1891 Boilers, when made (Main) 1891 (Donkey) 1891

No. of Main Boilers 2 Owners G. Thompson & Co. Port Aberdeen Voyage Australia

No. of Donkey Boilers 1 If Surveyed Afloat or in Dry Dock Royal Albert dock Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Steam Pressure in Main Boilers 160 in Donkey Boilers 160

Last Survey No. _____ Port _____

Particulars of Examination and Repairs (if any) Condition

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

CHARACTER, &c. for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned & expired.	Machinery and Boiler Surveys (including date of N.B., if any).
<u>100A1 Spawdk. 10.95.</u>		<u>L.M.C. 3-96</u>

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No.

Do. " Donkey " " " No.

If this was not done, state for what reasons? L.M.C. held.

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? No

Did the Surveyor examine the Safety Valves of the Main Boiler? Not adjusted

At what pressure were they afterwards adjusted under steam? No

Did the Surveyor examine the Safety Valves of Donkey Boiler? Not adjusted

To what pressure were they afterwards adjusted? No.

Has the propeller shaft been drawn and examined at this time? Complete

If the Survey is not complete state what arrangements have been made for its completion? Complete

Propeller & sea-connection fastenings examined & found in order.

General Observations, Opinion, and Recommendation:— This vessel's machinery, so far as seen, is in safe working condition and eligible, in my opinion, to remain as classed, without further record of survey.

Office or Registration Fee (per Sec. 27)..... £	:	:	Fees applied for
Survey Fee (per Section 28)..... £	:	:	18
Special Damage Fee (per Section 28)..... £	:	:	Received by me,
Travelling Expenses (if chargeable)..... £	:	:	18

R. Elliott.
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

*State if Certificate is required _____

Committee's Minute TUES 1 SEP 1896 FRI. 15 JAN 1897

Assigned as now



2043-24(3)04-Transfer Ink. (The Surveyors are requested not to write on or beside the space for Committee's Minute.)
 Has a Survey also been held on Ship? If so, if the Report sent now, or when will it be sent?

Insert Character of Ship and Machinery precisely as in the Register Book.

It is submitted that
this vessel is eligible to
remain AS CLASSED.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

End.
29.8.96.

[Faint, illegible handwritten text, likely bleed-through from the reverse side of the page.]

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2020
Lloyd's Register
Foundation