

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office

MON. 5 OCT 1896

Date of writing Report 4th Oct. 96 1896 When handed in at Local Office 18 Port of London

No. in Reg. Book. 977 Survey held at London Date, First Survey Last Survey 2nd Oct. 1896
on the Machinery of the Wood, Iron or Steel S.S. "Star of Victoria" Master W. Stevenson
Tonnage { Gross 3451 Net 2230 Vessel built at Belfast By whom Workman, Black & Co. When 1887
Registered Horse Power 325 Engines made at Glasgow When 1887 Boilers, when made (Main) 1887 (Donkey) 1887
No. of Main Boilers 2 Owners J. P. Barry & Co Port Belfast Voyage Australia
No. of Donkey Boilers 1
Steam Pressure in Main Boilers 160 If Surveyed Afloat or in Dry Dock Royal Albert dock
in Donkey Boilers 80
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.	Years Assigned	Years expired.	Machinery and Boiler Surveys (including date of N.B., if any).
100 A1.			B. 8.4.96
4.96.			L.M.C. 5.95.
S.S. Lon. N ^o 295.			

Last Survey No. 57626 Port Lon
Particulars of Examination and Repairs (if any) Condition

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

Has the propeller shaft been drawn and examined at this time?

If the Survey is not complete state what arrangements have been made for its completion?

Complete.
Propeller & sea-connection fastenings examined & found in order.

General Observations, Opinion, and Recommendation:— This vessel's machinery, so far as seen, is in safe working condition and eligible, in my opinion, to remain as classed without further record of survey.

Office or Registration Fee (per Sec. 27)	£	:	:	Fees applied for
Survey Fee (per Section 28)	£	:	:	18
Special Damage Fee (per Section 28)	£	:	:	Received by me,
Travelling Expenses (if chargeable)	£	:	:	18

*State if Certificate is required

Committee's Minute

Assigned

R. Elliott
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

It is submitted that
this vessel is eligible to
remain AS CLASSED.

U.S.
6.10.96

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.