

# Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report Oct 29 1896 When handed in at Local Office 18 Port of London  
No. in Reg. Book. 770 Survey held at London Date, First Survey Oct 26 Last Survey Oct 28 1896  
on the Machinery of the Wood, Iron or Steel J.S.S. Mohawk Master Gates  
Tonnage { Gross 5658 Net 3646 Vessel built at Belfast By whom Harland & Wolff, Lin When 1892 Boilers, when made (Main) 1892 (Donkey) 1892  
Registered Horse Power 611 Engines made at Do Owners African P.S. Co. Port London Voyage New York  
No. of Main Boilers 4 No. of Donkey Boilers - Steam Pressure in Main Boilers 175 lbs If Surveyed Afloat or in Dry Dock R. A. Dock  
in Donkey Boilers - (State name of Dock.)

Last Survey No. Port Particulars of Examination and Repairs (if any) Comp of S.S. M.C. 100 A.I. 1-96  
(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No.  
Do. " Donkey " " " Boilers already examined.  
If this was not done, state for what reasons?  
And what parts of the Boilers could not be thus thoroughly examined?  
Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?  
Did the Surveyor examine the Safety Valves of the Main Boiler? No.  
At what pressure were they afterwards adjusted under steam?  
Did the Surveyor examine the Safety Valves of Donkey Boiler? No.  
To what pressure were they afterwards adjusted?  
Has the propeller shaft been drawn and examined at this time? Completed.  
If the Survey is not complete state what arrangements have been made for its completion?  
Examined J.S.P. cylinders, Pistons, slide valves, pumps Condensers, & J.P. crank pins.

Due to wear clear. Port J.P. slide valve faced up.

General Observations, Opinion, and Recommendation:— This vessel's Machinery is now as far as seen in good condition & in my opinion the vessel is eligible for the record L.M.C. 9.96 as recommended in the London report. No. 58109.

Office or Registration Fee (per Sec. 27) £ : : Fees applied for 18  
Survey Fee (per Section 28) £ : :  
Special Damage Fee (per Section 28) £ : :  
Travelling Expenses (if chargeable) £ : : Received by me, 18  
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

State if Certificate is required  
Committee's Minute THURS 10 NOV 1896 FRI 11 DEC 1896 TUES 12 JAN 1897  
Assigned + L.M.C. 9.96 subject


Has a Survey also been held on Ship?  
If so, is the Report sent now, or when will it be sent?

Insert Character of Ship and Machinery precisely as in the Register Book.

\*Certificate to be sent to.

2309.—15/8/99.—Transfer Int.

The Surveyors are requested not to write in or below the space for Committee's Minute.





Port I. P. slide valve faced up - due to wear <sup>near</sup>

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that  
this vessel is eligible for  
**THE RECORD.** + L. M. C. 9. 96 subject  
to the screw shafts being examined  
before the end of Aug. 1897

R. B.  
6/11/96.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2020

Lloyd's Register  
Foundation