

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office

SAT 16 JAN 1897

Date of writing Report *15 Jan 97* When handed in at Local Office *15 Jan 97* Port of *London*
No. in Reg. Book. *357* Survey held at *London* Date, First Survey *9 Jan 97* Last Survey *15 Jan 1897*
on the Machinery of the Wood Iron or Steel *S. N. Woodborn* Master *G. Abraham*
Tonnage { Gross *3521* Net *2221* Vessel built at *U. C. C.* By whom *W. H. Richardson* When *1891* 7
Registered Horse Power *445* Engines made at *W. H. Richardson* When *91* Boilers, when made (Main) *91* (Donkey) *91*
No. of Main Boilers *2* Owners *W. H. Richardson* Port *London* Voyage *Australia*
No. of Donkey Boilers *1* If Surveyed Afloat or in Dry Dock *U. C. C. Dry Dock* Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
Steam Pressure in Main Boilers *155 lb.* in Donkey Boilers *50*

Last Survey No. _____ Port _____

Particulars of Examination and Repairs (if any) *Amund + 100 At. 896 + 100 At. 7.95*

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

Has the propeller shaft been drawn and examined at this time? *No.*

If the Survey is not complete state what arrangements have been made for its completion? *Complete.*

Hand done: Propeller Stern-bush and outside fastenings of Sea connections examined and found in good condition.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,95, B.&M.S. 9,95 or L.M.C. 9,95, 140 lb., F.D., &c.)

The machinery of this vessel so far as now examined is in good condition and, in my opinion, eligible to remain as classed without fresh records.

Office or Registration Fee (per Sec. 27)	£	:	:	Fees applied for
Survey Fee (per Section 28)	£	:	:	15
Special Damage Fee (per Section 28)	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	Received by me, 15

*State if Certificate is required

Committee's Minute

TUES 26 JAN 1897

Assigned

as now

D. R. R. R.
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.



Lloyd's Register Foundation

LON711-0318

It is submitted that
this vessel is eligible to
remain AS CLASSED.

R.L.
23/1/97.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019
Lloyd's Register
Foundation