

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office

FRI. 4 JUN 1897

Date of writing Report 3 June 97 When handed in at Local Office 18 Port of London

No. in Reg. Book 298 Survey held at London Date, First Survey 1876 Last Survey 2 June 1897

on the Machinery of the Wood, Iron or Steel S.S. "Petrel" Master W Taylor

Gross Tonnage 739 Net 462 Vessel built at Aberdeen By whom Hall Russell & Co When 1876 Boilers, when made (Main) 1876 (Donkey) 1876

Registered Horse Power 99 Engines made at Aberdeen Owners General Steam Nav Co Port London Voyage Amsterdam

No. of Main Boilers one No. of Donkey Boilers one Steam Pressure in Main Boilers 65 lb in Donkey Boilers 50 lb Surveyed Afloat or in Dry Dock Brewer's Lier (State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
+ 100 A. 1. 96		L.M. 1. 95
S.S. Lon No 3 - 10.89		B.S. 1. 96
S.S. Lon No 1 - 95		

Last Survey No. 58698 Port Lon

Particulars of Examination and Repairs (if any) Comp 7 BS

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No

Do. " Donkey " " No

If this was not done, state for what reasons? Recently examined

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? No

Did the Surveyor examine the Safety Valves of the Main Boiler? No

At what pressure were they afterwards adjusted under steam? Not-adjusted

Did the Surveyor examine the Safety Valves of Donkey Boiler? No

To what pressure were they afterwards adjusted? blow 50 lbs

Has the propeller shaft been drawn and examined at this time? No

If the Survey is not complete state what arrangements have been made for its completion? Complete

Examined repairs to Donkey Boiler completed as recommended (patches fitted on shell & firebox) same satisfactory. Examined Main Boiler under steam and adjusted safety valve to working pressure blow 50 lbs.

General Observations, Opinion, and Recommendation: The Machinery of this vessel,
(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9.95, B.&M.S. 9.95 or L.M.C. 9.95, 140 lb., F.D., &c.)
so far as seen, is now in a safe working condition and eligible, in my opinion, to have B.S. 3.97 Recorded in the Register of this Society, as per London Report-No 58698.


Office or Registration Fee (per Sec. 27)	£	:	:	Fees applied for
Survey Fee (per Section 28)	£	:	:	18
Special Damage Fee (per Section 28)	£	:	:	Received by me,
Travelling Expenses (if chargeable)	£	:	:	10

*State if Certificate is required ✓

Committee's Minute TUES 8 JUN 1897

Assigned BDH 97

Thomas R Blackie
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.



L. 30, is the Report sent now, or when will it be sent?

Insert Character of Ship and Machinery precisely as in the Register Book.

*Certificate to be sent to

Anchor Bole repaired

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that
this vessel is eligible for
THE RECORD. B.S. 4,97

SL
4/6/97

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation