

Report of Survey for Repairs, &c., of Engines and Boilers.

MON 26 JUL 1897

Date of writing Report *14th July* 18 *97* When handed in at Local Office *16th July* 18 *97* Port of *London*
 No. in Reg. Book *503* Survey held at *London* Date, First Survey *18th July* Last Survey *21st July* 18 *97*
 on the Machinery of the *Wood, Iron or Steel* *S. S. Port Pirie* Master *H. Lewis*
 Tonnage { Gross *3020* Net *1929* Vessel built at *Niell* By whom *R. W. Hawthorn & Co.* When *1886* YEAR. MONTH.
 Registered Horse Power *382* Engines made at *"* When *86* Boilers, when made (Main) *86* (Donkey) *86*
 No. of Main Boilers *3* Owners *W. Milburn & Co.* Port *London* Voyage *Australian Port*
 No. of Donkey Boilers *1* If Surveyed Afloat or in Dry Dock *Afloat - in Dry Dock* Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
 Steam Pressure in Main Boilers *150 lb* in Donkey Boilers *65 lb*

Last Survey No. _____ Port _____

Particulars of Examination and Repairs (if any) *Condition +100 A. 1. 7. 96 + L.M.C. 12. 94*

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

Has the propeller shaft been drawn and examined at this time? *No.*If the Survey is not complete state what arrangements have been made for its completion? *Complete.*

Now done! - Propeller and outside fastenings of the Sea Connections and the Stern-bush examined. Latter worn '88. Saw officially regarding exam of the Donkey Boiler. This Boiler is not to be used again and no preparations now made for its examination.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9.95, B.&M.S. 9.95 or L.M.C. 9.95, 140 lb. F.D., &c.)

The Machinery of this vessel so far as now seen is in good condition and in my opinion eligible to remain as classed subject to the Donkey Boiler not being used again. The fresh record of B.S. is respectfully recommended.

Office or Registration Fee (per Sec. 27) £ : : Fees applied for
 Survey Fee (per Section 28) £ : : 18
 Special Damage Fee (per Section 28) £ : :
 Travelling Expenses (if chargeable) £ : :
 Received by me, _____

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

State if Certificate is required

Committee's Minute

FRI. 6 AUG 1897

TUES. 17 AUG 1897

TUES. 28 JUN 1897 TUES. 2 NOV 1897 FRI. 20 AUG 1897

Assigned

283.97 subgr

Lloyd's Register Foundation

WON713-0146

It is submitted that
this vessel is eligible for
THE RECORD.

B. I. 397 subject to
the Grady Boiler not being used
again
Owners to be advised

Full
4/8/97

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation