

Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report 31st July 1897 When handed in at Local Office 2nd August 1897 Port of London
(Received at London Office TUES. 3 AUG 1897)
No. in Reg. Book. 615 Survey held at London Date, First Survey and Last Survey 30th July 1897
(No. of Visits 1)
on the Machinery of the Wood, Iron or Steel S.S. Merionethshire Master Davis
Tonnage { Gross 3012 Vessel built at Sweden By whom Ed. J. B. & Co. Ltd When 1895 / 1
Net 1950 Engines made at " When '95 Boilers, when made (Main) '95 (Donkey) '95
Registered Horse Power 326 Owners Arthur Holt & Co. Port London Voyage China & Japan
No. of Main Boilers 2 If Surveyed Afloat or in Dry Dock In Dry Dock
No. of Donkey Boilers 1 (State name of Dock.)
Steam Pressure—
in Main Boilers 160 lb.
in Donkey Boilers 100 lb.

Last Survey No. Port
Particulars of Examination and Repairs (if any) In Dry Dock + 100 A. 1. 97
Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?
Do. " Donkey " " "
If this was not done, state for what reasons?
And what parts of the Boilers could not be thus thoroughly examined?
Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?
Did the Surveyor examine the Safety Valves of the Main Boiler?
At what pressure were they afterwards adjusted under steam?
Did the Surveyor examine the Safety Valves of Donkey Boiler?
To what pressure were they afterwards adjusted?
Has the propeller shaft been drawn and examined at this time? No.
If the Survey is not complete state what arrangements have been made for its completion? Complete.
Propeller Outside fastenings of the Sea Connections and the Stern-bush examined, latter down 1/8 of an inch.

General Observations, Opinion, and Recommendation:—
(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,95, B.&M.S. 9,95 or L.M.C. 9,95, 140 lb., F.D., &c.)
The Machinery of this vessel is in good Condition and in my opinion, eligible to remain as classed. Without fresh record.

Office or Registration Fee (per Sec. 27) £ : : Fees applied for
Survey Fee (per Section 28) £ : :
Special Damage Fee (per Section 28) £ : :
Travelling Expenses (if chargeable) £ : :
State if Certificate is required
Committee's Minute FRI 6 AUG 1897
Assigned As above
Received by me, Christine
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

*It is submitted that
this vessel is eligible to
remain as CLASSED.*

LD
5/8/97

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation