

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office

THUR, 2 SEP 1897

Date of writing Report Sept 1st 97 When handed in at Local Office 18 Port of London
No. in Reg. Book. 781 Survey held at London Date, First Survey Aug 31 Last Survey Sept 1st 1897
on the Machinery of the Wood, Iron or Steel S.S. Mississippi Master Canna
Tonnage { Gross 3732 Net 2388 Vessel built at Belfast By whom Harland & Wolff When 1890 YEAR. MONTH.
Registered Horse Power 390 Engines made at London Boilers, when made (Main) 1890 (Donkey) 1890
No. of Main Boilers 2 Owners Atlantic Transport Co. Ltd Port London Voyage New York
No. of Donkey Boilers 1 If Surveyed Afloat in Dry Dock N.A. Dry Dock
Steam Pressure in Main Boilers 180 lbs in Donkey Boilers 90 lbs
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Survey No. 100 A. 1. 7. 97 Port London
Particulars of Examination and Repairs (if any) Docking
Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No.
Do. " Donkey " " " " No.
If this was not done, state for what reasons? Survey not due
And what parts of the Boilers could not be thus thoroughly examined? Completed.
Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? Completed.
Did the Surveyor examine the Safety Valves of the Main Boiler? ✓ At what pressure were they afterwards adjusted under steam? ✓
Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓ To what pressure were they afterwards adjusted? ✓
Has the propeller shaft been drawn and examined at this time? No If spare propeller shaft fitted, state whether new? ✓
If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? Completed.

Hammed propeller, stem bush, & sea connections fastenings; Propeller nut hardened up & new copper fitted.

General Observations, Opinion, and Recommendation:— This vessel's Machinery is now as far as seen in good condition & in my opinion the vessel is eligible to remain as classed.

Registration Fee (per Sec. 27) £ : : Fees applied for
Fee (per Section 28) £ : :
Damage Fee (per Section 28) £ : :
Expenses (if chargeable) £ : :
Received by me, 18
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate is required
Committee's Minute
Signed As now
TUES, 7 SEP 1897

It is submitted that
this vessel is eligible to
remain as CLASSED

E.L.
3.9.97

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation